

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI21013015/UTY3E2

Date: 18/03/2022

REFERENCE

Insured/Claimant: LAM KIM SAN Policy No: DMPCSNW00260332100
Date of Loss: 21/12/2021 Nature of Claim: OD Claim No: SNM21D207478/C01/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE7272B**
Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UJN8889
Reg. Date: 27/08/2020 (Man. Year: 2020) Chassis No: MMBSTA13AMH000579
Colour: Silver Odometer: 8567 km
Engine Capacity: 1193 cc
Market Value/New Car Price: S\$66,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R15 Rear Tyre Size: 185/55 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,820.00	6,059.00	761.00	11.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,419.60	646.80	772.80	54.44
Paintwork Labour	854.11	783.29	70.82	8.29
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,093.71	7,489.09	1,604.62	17.65
- Excess (S\$)	0.00	200.00	-200.00	
(S\$)	9,093.71	7,289.09	1,804.62	19.84
+ GST 7.00/7.00% (S\$)	636.56	510.24	126.32	19.84
Nett Amount (S\$)	9,730.27	7,799.33	1,930.94	19.84

INSPECTION

Date of Assignment: 22/12/2021 Present Location: Jin Auto Services Pte Ltd (Defu)
Date Inspected: 23/12/2021 Inspected At: Jin Auto Services Pte Ltd (Defu)
Estimated Period of Repair: 6.0 days Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Mar 2022)	
Parts:	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGE7272B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TOTAL PARTS		6,161.00 F	*5,468.00 F
2	1		*SUNDRY	Necessary	100.00 F	*100.00 FS
3	1		*FRONT NUMBER PLATE	Broken	-	*35.00 FS
Supplementary #1						
4	1		*1007 Shroud, Cooling Fan Supplementary \$90.00	Cracked	90.00 F	*90.00 F
5	1		*1008 Duct, A/CInr Intake Supplementary \$60.00	Cracked	60.00 F	*60.00 F
6	1		*1009 Headlamp Panel LH Supplementary \$38.00	Bent	38.00 F	*38.00 F
7	1		*1010 Headlamp Panel RH Supplementary \$38.00	Bent	38.00 F	*38.00 F
8	1		*1011 Fr Bumper Garnish LH Supplementary \$50.00	Distorted	50.00 F	*50.00 F
9	1		*1012 Fr Bumper Garnish RH Supplementary \$50.00	Distorted	50.00 F	*50.00 F
10	1		*1013 Fr Bumper side LH Ga Supplementary \$65.00	Deformed	65.00 F	*65.00 F
11	1		*1014 Fr Bumper side RH Ga Supplementary \$65.00	Deformed	65.00 F	*65.00 F
12	1		*1013 Fr Bumper side RH Ga Supplementary \$65.00	Repeated	65.00 F	*- F
13	1		*1010 Headlamp Panel RH Supplementary \$38.	Repeated	38.00 F	*- F
Total Parts (\$\$)					6,820.00	6,059.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINTWORK LABOUR CHARGE	New	854.11	783.29
<u>Labour Items</u>				
2	TOTAL LABOUR CHARGE	New	1,419.60	646.80
Gross Labour Cost (S\$)			2,273.71	1,430.09

Report was unsubmitted during this print-out.

< END OF ESTIMATES >