

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

37 LOYANG WAY, SINGAPORE 508734

VEHICLE NO : GBK3790B

MAKE & MODEL : NISSAN NV350 PANEL VAN 2.5 5MT 5DR

CHASSIS NO : JN1MC2E26Z0031834

DATE:

22 Dec 2021

CLAIM TYPE :

TP CLAIM

D.O.A:

16 Dec 2021

TO : AIG ASIA PACIFIC INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

i/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT LIST PRICE	TOTAL LIST PRICE
1	1	REAR BUMPER		\$ 667.20	\$ DT / 667.20
2	3	REAR BUMPER SIDE CLIP LH		\$ 12.10	\$ nec / 36.30
3	1	TAILGATE		\$ 2,280.00	\$ DT / 2,280.00
4	1	TAILLAMP LH		\$ 224.80	\$ C/a / 224.80
5	1	TAILGATE LOGO		\$ 115.20	\$ nec / 115.20
6	1	TAILGATE EMBLEM NV350 URBAN	101-3	\$ 156.00	\$ nec / 156.00
7	1	REAR END PANEL OUTER		\$ 360.90	\$ 1. Xr 360.90
8	1	REAR FENDER LH		\$ 1,793.40	\$ 1. Xr 1,793.40
9	1	TAIL LAMP PANEL LH		\$ 465.30	\$ 1. Xr 465.30
10	1	REAR REINFORCEMENT PANEL INNER LH		\$ XSVL 464.10	\$ 1. XSVL 464.10
11	1	TAILGATE FEMALE DOVETAIL		\$ 85.70	\$ XSVL 85.70
12	1	TAILGATE MALE DOVETAIL		\$ 49.60	\$ 1. XSVL 49.60
				\$ 6,674.30	\$ 6,698.50

TOTAL PRICE	\$ 6,698.50
LESS 10%	\$ 669.85
SUB TOTAL PRICE	\$ 6,028.65

No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
1	1	SEALANT		\$ 80.00	\$ 50 / 80.00
2	1	70 KM/H STICKER		\$ 20.00	\$ 20.00
3	1	PAN PACIFIC METAL PLATE		\$ 80.00	\$ 40 / 80.00
4	1	REVERSE SENSOR		\$ 200.00	\$ 1. XSVL / 200.00
5					\$ -
TOTAL S/NETT				\$ 380.00	\$ 380.00

Labour Charges

1	To cut/weld rear fender panel beat & inner panel, remove & replace damaged parts.	\$ 1,400.00	700
2	To apply anti rust coat and Tuff Kote repaired areas.	\$ 100.00	30
3	To check and rectify lighting & wiring.	\$ 120.00	30
4	To remove & replace reverse sensor.	\$ 120.00	30
5	To remove and refit tailgate windscreen to facilitate repair	\$ 150.00	170
6	To transfer tailgate parts and mechanism to new tailgate	\$ 150.00	50
7	To Spray painting for Rear LH Portions & affected areas.	\$ 1,200.00	600

TOTAL LABOUR

\$ 3,240.00

Total Cost of Repairs

\$ 9,648.65

(Total parts + Total S/Nett + Total Labour Cost)

Theran

Theran@LKKAuto.com

82235769

22/12/21 1500

45 4 days
up

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: