

LKK Auto Consultants hence notify the Rep. of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

祥輝汽車修理

SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

not followed

then

27/12/21

1/2 \$2050

4 days. Take the After rep.

Date, 24/12/21

Vehicle No: SJN 213K

1	1PC Rear bumper	20/02	\$482.03	/
2	1PC Rear bumper sponge	10m	\$110.08	/
3	2PCS Bumper side retainer	@ \$45.23	11 \$90.46	X
4	2PCS Bumper reflector	@ \$66.02	11 \$132.04	X
5	1PC Rear boot lid	2	\$654.23	X
6	1PC Rear boot lid w/strip	7m	\$125.03	/
7	1PC Rear boot inner lock	8u	\$108.03	X
8	1PC Rear boot reflector	11	\$145.23	X
9	1PC Tail lamp	11	\$303.25	X
10	1PC End panel	20	\$517.23	/
11	1PC End panel top garnish	2m	\$202.14	/
Less 20% GST			\$2869.75	
			\$573.95	
			\$2295.80	

S/ Nett Item:-

1	10PCS Bumper C/P	@ 5.00	50.00	✓
2	1set Reverse sensor	shotted	\$240.00	200
			\$290.00	

Labour Charges:-

1	To remove, replace reverse sensor	\$60.00	50
2	To spray painting	\$1200.00	600
3	To remove, replace boot lid rear bumper & end panel	\$1200.00	600
Total:			\$5045.80

p-1436.57

25%

1077.38

2577.78