

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 213K

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DENTED / DEFORMED	482.03	482.03
1	REAR BUMPER SPONGE (CONSISTENT)	TORN	110.08	110.08
2	BUMPER SIDE RETAINER @\$45.23 (CONSISTENT)	NOT NECESSARY	90.46	-
2	BUMPER REFLECTOR @\$66.02 (CONSISTENT)	NOT NECESSARY	132.04	-
1	REAR BOOT LID (CONSISTENT)	TO REPAIR SEE LABOUR	654.23	-
1	REAR BOOT LID W/STRIP (CONSISTENT)	TWISTED	125.03	125.03
1	REAR BOOT INNER LOCK (CONSISTENT)	SERVICEABLE	108.03	-
1	REAR BOOT REFLECTOR (CONSISTENT)	NOT NECESSARY	145.23	-
1	TAIL LAMP (CONSISTENT)	NOT NECESSARY	303.25	-
1	END PANEL (CONSISTENT)	DENTED	517.23	517.23
1	END PANEL TOP GARNISH (CONSISTENT)	TWISTED	202.14	202.14
	LESS 20% DISCOUNT		-573.95	-
	LESS 25% DISCOUNT		-	-359.13
			2,295.80	1,077.38
	SPECIAL NETT ITEMS			
10	BUMPER CLIP @\$5.00 (SN) (CONSISTENT)	NECESSARY	50.00	50.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	240.00	200.00
			290.00	250.00
	<u>LABOUR</u>			
	TO REMOVE, REPLACE REVERSE SENSOR.		60.00	50.00
	TO SPRAY PAINTING.		1,200.00	600.00
	TO REMOVE, REPLACE BOOT LID REAR BUMPER & END PANEL. INCLUSIVE OF THE REPAIR OF REAR BOOT LID.		1,200.00	600.00
			2,460.00	1,250.00
	GRAND TOTAL		5,045.80	2,577.38

Report Ref No. CS/ASM21013019/Uty3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,050.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/ASM21013019/Uty3e2

CHUA KANG SENG

Licensed Appraiser