



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: HO WINNIE			Ref: CS/ASM21013019/Uty3e2 Date: 11/01/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 2002U	Veh. Inspected	SJN 213K
	Policy No.		Coverage (\$)	0.00
	Claim No.	S1M03OUZ	Excess (\$)	0.00
	Assign From	HO WINNIE	Assign Date	22/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	MR053ZEE106130123	Colour	GREY
	Odometer	228494 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/12/2021	Inspection Date	27/12/2021
	Survey held at	SIANG HUI MOTOR WORKS BLK 3006 UBI ROAD 1 #01-338 SINGAPORE 408700		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	