

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013021/RQY3N2**Date:** 07/02/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00053792102

Claimant Vehicle No : SJS9451D**Insured Vehicle No :** GBJ5544M

Date of Loss: 16/12/2021

Nature of Claim: TP

Claim No: SNM21D207362/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJS9451D**

Make & Model: VOLKSWAGEN BEETLE, 1.2 (A)

Engine No: CYV642150

Reg. Date: 27/02/2019 (Man. Year: 2018)

Chassis No: WVVZZZ16ZKM708121

Colour: White

Odometer: 36498 km

Engine Capacity: 1197 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45 ZR18	Rear Tyre Size:	235/45 ZR18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,460.42	1,460.42	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	2,120.00	3,560.00	62.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,140.42	3,580.42	3,560.00	49.86
+ GST 7.00/7.00% (S\$)	499.83	250.63	249.20	49.86
Nett Amount (S\$)	7,640.25	3,831.05	3,809.20	49.86

INSPECTION

Date of Assignment: 11/01/2022

Date Inspected: 24/12/2021

Inspected At:

Volkswagen Centre Singapore (HQ)
247 Alexandra Road
Singapore 159934

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Feb 2022)
Parts:	143	VOLKSWAGEN BEETLE 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS9451D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER FOR BUMPER PRIMED	Deformed	1,380.42 FS	*1,380.42 FS
2	1		*NUMBER PLATE	Bent	80.00 FS	*80.00 FS
					Total Parts (S\$)	1,460.42
						1,460.42

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	480.00	480.00
2	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
3	LABOUR	New	2,520.00	840.00
4	SPRAY PAINTING	New	2,400.00	800.00
Gross Labour Cost (\$\$)			5,680.00	2,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >