



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200593

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 28/01/2022
Reference CC4/FCI21013027/Rga3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SMS 6563Z
Insured Veh. GBE 9693R
Claim No. D21003470MFCV
Policy No.
Accident Date 20/12/2021
Inspection Date 23/12/2021

Description	Total
Survey Inspection	290.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	290.00
GST (7%)	20.30
Grand Total	310.30

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21013027/Rga3q2 Date: 28/01/2022 Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 9693R	Veh. Inspected	SMS 6563Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003470MFCV	Excess (\$)	0.00	
Assign From	ESTHER	Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN TOURAN 1.4 TSI CL	c.c	1395	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WVGZZZ1TZKW072604	Colour	GREY	
Odometer	61342 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45Z R18	FALKEN	6 mm	
L/H Front Tyre	225/45Z R18	FALKEN	6 mm	
R/H Rear Tyre	225/45Z R18	FALKEN	6 mm	
L/H Rear Tyre	225/45Z R18	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/12/2021	Inspection Date	23/12/2021	
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMS 6563Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER FOR BUMPER PRIMED (SN)	DEFORMED	1,443.25	1,443.25
1	SPOILER SATIN BLACK (SN)	CUT	332.69	332.69
4	RIVET (SN)	NECESSARY	4.76	4.76
1	GUIDE PIECE LHR BUMPER SIDE BRACKET (SN)	NOT NECESSARY	34.85	-
1	GUIDE PIECE RHR BUMPER SIDE BRACKET (SN)	NOT NECESSARY	34.85	-
1	GUIDE PIECE LHR BUMPER INNER BRACKET (SN)	NOT NECESSARY	42.63	-
1	GUIDE PIECE RHR BUMPER INNER BRACKET (SN)	NOT NECESSARY	42.63	-
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	552.19	-
1	INSCRIPTION BRIGHT CHROME TOURAN EMBLEM (SN)	NECESSARY	74.51	74.51
1	VW SIGN BLACK /BRIGHT CHRO (SN)	NECESSARY	108.68	108.68
			2,671.04	1,963.89
	<u>LABOUR</u>			
	B&P MECHANICAL SERVICE .		280.00	280.00
	B&P DIAGNOSIS AND PROGRAMMING .		480.00	480.00
	LABOUR .		2,520.00	1,680.00
	SPRAY PAINTING .		2,400.00	1,600.00
			5,680.00	4,040.00
GRAND TOTAL			8,351.04	6,003.89
RECOMMENDED COST OF REPAIRS				6,003.89

Report Ref No. CC4/FCI21013027/Rga3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 6563Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMS 6563Z

RE-INSPECTION

