



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKG6339S

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **54176**
Reg No/Reg Date **SKG6339S / 06/12/2019**
Date In/Mileage **/ 0**
Chassis No **WDD2130802A7002826**
Engine No **26492080012216**
Make/Model **MB/E 200 SEDAN AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator	Description of Goods / Services	Qty	Unit Price	Disc%	Amount
WL001605	Credit	21/12/2021/ 17:10	AQ	305 / Alan Quek Ai Lun					
<p>M BPNSUN POLICY NO/ACC DATE : 1900252912 // 21-12-2021 DRIVE IN: 21-12-2021 // TP CAR NO: XE1092S (LONPAC INSURANCE) DATE IN/DATE SURVEY: BY/AUTHORIZED ON :</p> <p>A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT</p> <p>A BPILAB REMOVE & INSTALL PETROL TANK FILLING HOSE FOR NECESSARY REPAIR OR REPL</p> <p>A BPILAB RENEW REAR WINDSHIELD</p> <p>S BPNSUB SUPPLY & TRANSFER 1PC REAR WINDSHIELD SOLAR FILM PURCHASE ORDER NO:</p> <p>S BPNSUB SUPPLY & TRANSFER 1PC REAR RIGHT RIM PURCHASE ORDER NO:</p> <p>A BPILAB INSPECT & CONDUCT WHEEL ALIGNMENT.NETT</p> <p>A BPILAB REMOVE & INSTALL REAR BOOT LID COMPARTMENT INTERIOR</p> <p>A BPILAB REMOVE & REPLACE REAR RIGHT FENDER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.</p> <p>A BPIRES RESPRAY REAR RIGHT DOOR, REAR RIGHT FENDER, REAR BUMPER & REAR END PANEL</p> <p>M RH/R DISC WHEEL</p> <p>M REAR WINDSHIELD</p> <p>M REAR WINDSHIELD SEAL</p> <p>M GLAZING REPAIR KIT</p> <p>M RH/R FENDER</p>									
								0.10	380.00
									300.00
								0.07	560.00
									300.00
									60.00
									540.00
									1440.00
									4800.00
									2400.00
						1.00	779.44	00.00	779.44
						1.00	1508.32	00.00	1508.32
						1.00	41.06	00.00	41.06
						2.00	160.11	00.00	320.22
						1.00	2344.99	00.00	2344.99

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKG6339S

LONPAC INSURANCE BHD

MOTOR CLAIM DEPARTMENT
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
62507388

Vehicle & Document Information

WIP No **54176**
Reg No/Reg Date **SKG6339S / 06/12/2019**
Date In/Mileage **/ 0**
Chassis No **WDD2130802A7002826**
Engine No **26492080012216**
Make/Model **MB/E 200 SEDAN AVANTGARDE**
Colour/Trim **029 992 Selenite Gr/ 042 201 Leather Bla**

Account No	Terms	Date/Time Printed	CSE	Operator				
WL001605	Credit	21/12/2021/ 17:10	AQ	305 / Alan Quek Ai Lun				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RH/R WHEEL ARCH COVER				1.00	195.30	00.00	195.30
M	RH/R FENDER AIR FLAP				1.00	27.17	00.00	27.17
M	ADHESIVE SEALANT				1.00	776.81	00.00	776.81

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Authorized signatory and company stamp

Nett **16,773.31**
7% GST on **16773.31** **1174.13**
Total Payable 17,947.44

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany