

Kenneth

A464 210130291Ke

ASSIGNMENT

C

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 863k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Mandy

Date / Time Action / Instruction

F12 71 Reg 810,300. Concl

Date/Time, File Pass to?

☐ : Prel. Report

1)

Date/Time, File Return to?

☐ : Final Report

2)

Report Format :

Lump Sum / I.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$ _____

Fees _____

Others _____

TOTAL

Veh No: SIFR 991PA Yr Regn: 11, 13Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota XF c.c. 2179Colour: M.P. Blue A/C: Insured / Std / NI / NASp. Reading: 192900 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SATAC 0565DD U00306Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD / Rim or

Tyre Size: F: _____

R: 245/45R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 18/12/21

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 22/12/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

MOTOR EDGEVANTAGE PTE LTD

160 Sin Ming Drive, Sin Ming AutoCity #03-01/02, Singapore 575722 & GST 201534758N

+65 6453 7683 clientservices@edgevantage.com www.edgevantage.com

To:

Mr Robin Chong

SFR9919A, JAGUAR, XF 2.2 I4D AUTO ABS D/AB 2WD 4DR HID TC

Attn: Robin Chong (91896627)

87783280 mandy

Work Order

Job No. : WJ2110249

Date : 22/10/2021

Mil in (KM) : 192900

Time in : 18/12/2021 19:00

Time out : 24/12/2021 08:00

T	Job Description	Operation	Quantity	UOM	Unit Price	Amt
Essential Works						
P	Jaguar SRS airbag module XF	Activate	2.00	PCS	1,859.00	3,718.00 ✓
P	Jaguar bonnet hinge RH XF	DiT	1.00	PCS	210.00	210.00 ✓
P	Jaguar bonnet hinge LH XF	DiT	1.00	PCS	210.00	210.00 ✓
S	Jaguar front bonnet lock RH XF	Re	1.00	PCS	310.00	310.00 ✓
S	Jaguar front bonnet lock LH XF	Re	1.00	PCS	310.00	310.00 X
P	Jaguar bonnet strut XF	Re	2.00	PCS	224.00	448.00 X
P	Jaguar front impact sensor XF	Re	2.00	PCS	185.00	370.00 ✓
S	Jaguar headlamp assembly XF	CM	1.00	PCS	2,860.00	2,860.00 ✓
S	Jaguar front headlamp support panel XF	Re	1.00	PCS	1,980.00	1,980.00 ✓
S	Jaguar front bumper assembly XF	Re/CM	1.00	PCS	2,170.00	2,170.00 ✓
P	Jaguar front bumper lower grille RH XF	Re	1.00	PCS	273.00	273.00 X
S	Jaguar front bumper side bracket XF	DiT	1.00	PCS	85.40	85.40 ✓
S	Jaguar front bumper tow eye cover XF	CM	1.00	PCS	73.60	73.60 ✓
S	Jaguar front bumper Lid RH XF	CM	1.00	PCS	84.90	84.90 ✓
S	To remove, install, install front bonnet LH and RH air bags modules, front both bonnet hinges, bonnet strut, bonnet locks, impact sensors, front bumper, headlamp, front support panel	108	1.00		1,200.00	1,200.00 750/
S	To putty, spray paint front bumper, both front hinges, front bonnet, front fender RH		1.00		1,600.00	1,600.00 1000/
S	To download software on airbag module, check wiring, contact diagnostic using equipment tools to run through air bag (SRS) system		1.00		400.00	400.00 250/
S	Towing charges on Dolly from Upper Thomson Road to 'Workshop (Accident tow)		1.00	(Bill)	140.00	140.00 100/

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Remarks:

Accident
Cash card

Hennerth
96910863

Not with the
L1Pw @ 10,300/2
Running After Paint

This is a computer generated Work Order. No Signature is required.

6 days Subtotal 16,442.90
GST 7.0% 1,151.00
Total 17,593.90