



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SHENG YEE ZHER (SHENG YIZHE)	Cust No/Name /SHENG YEE ZHER (SHENG YIZHE)
BLK 103 LENGKONG TIGA	Reg No/Reg Date EK52H / 13/11/201
#12-379	Date In/Mileage / 0
SINGAPORE 410103	Chassis No GF7W0600200
Contact No Mobile: 96956565	Engine No 4J11AA4180
	Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	22/12/2021/ 18:28	BLC	442 / CocoLu	19078			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
E PNT88000	RENEW REAR BUMPER, REPAIR TAILGATE REAR LH FENDER							450 900.00
E PNT98000	SPRAY PAINT FOR REAR BUMPER, TAILGATE REAR LH FENDER							700.00
M SUNDRY	Sundry							20.00
E PNT88000	REMOVE & INSTALL PARKING SENSOR							80.00
A 54900099	CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							120.00
M FACE,RR BUMPER	cut				1.00	1018.00	00.00	783.86 1018.00
M EXTENSION,RR BUMPER	cut				1.00	292.00	00.00	224.84 292.00
M REINFORCEMENT,RR BUMPER,LH	? Xan				1.00	79.00	00.00	79.00
M BRKT,R/BMPR FACE SIDE,LH	? Xan				1.00	12.00	00.00	12.00
M MOULDING,RR BUMPER,LH	? Xan				1.00	106.00	00.00	106.00
M LAMP ASSY,COMB,RR LH	? Xan				1.00	603.00	00.00	464.31 603.00
M REFLECTOR,TAIL LAMP,LH	? Xan				1.00	100.00	00.00	100.00
M LAMP ASSY,TAIL,LH	? Xan				1.00	506.00	00.00	389.61 506.00

SURVEYOR NAME: Rasul - 4p 90010068

SURVEYOR SIGNATURE: [Signature]

DATE: 27/12/21 @ 1450

REMARKS: 4 days

EXCESS: TBA / Renew

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm &amp; accepted by

Nett	4,566.00
7% GST on	4566.00
	319.62

Total Payable 4,885.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.