



CYCLE & CARRIAGE

AIG - OD CLAIM
SURVEY: 27/12/21
LKK - PASUL

VEHICLE NO : EK 52 H

MODEL : MIT/OUTLANDER 2.0 MODERN

WIP : 19078

Material	:	\$	<u>1,862.63</u>
Labour	:	\$	<u>1,400.00</u>
Sub-Total	:	\$	<u>3,262.63</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>2,662.63</u>
GST 7%	:	\$	<u>186.38</u>
Grand Total	:	\$	<u>2,849.01</u>
Finalise By/Date :	<u>Umy ON 05/01/22</u>		

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 04 WORKING DAYS + 2 days (wk. end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 27/12/2021	Cust No/Name	/SHENG YEE ZHER (SHENG YIZHE)
	Reg No/Reg Date	EK52H / 13/11/2018
	Date In/Mileage	27/12/2021/ 47813
	Chassis/Package	GF7W0600200 /#F
	Engine No	4J11AA4180
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	05/01/2022/ 16:46	BLC	884 / Lauro Songcuan	19078

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR REAR FENDER LH				450.00 ✓
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR FENDER LH				700.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00 ✓
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00 ✓
X EXC EXCESS				-600.00
X FACE,RR BUMPER ✓	1.00	1018.00	23.00	783.86 ✓
X EXTENSION,RR BUMPER ✓	1.00	292.00	23.00	224.84 ✓
X LAMP ASSY,COMB,RR LH ✓	1.00	603.00	23.00	464.31 ✓
X LAMP ASSY,TAIL,LH ✓	1.00	506.00	23.00	389.62 ✓
Z TEXT AIG - OD CLAIM DOA: 21/12/2021 SURVEY: RASUL (LKK) 27/12/2021 04 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle & Carriage!</i>				

Parts	1,862.63		Nett	2,662.63
Labour	1,380.00	7% GST on	2662.63	186.38
Standard Menu	0.00			
Specialist Job	0.00			
Diagnostics Job	0.00		Total Payable	2,849.01
Sundry/Others	-580.00			
Total(w/o GST)	2,662.63			

This is not an official tax invoice.
This is a computer generated document, no signature is required.

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21121-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W XTX 2019MY

For No: EX52H
Before use MUT-3 use unit to check all the found

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs		
OSS	OSS_9588000B		No DTCs		
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error		
ACC/FCM	ACCSCFCM_4B080000		Non-equipped System or Communication Error		
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error		
EPB	EPB_4C080000		No DTCs		
Gateway	GW_C1000000		Non-equipped System or Communication Error		
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error		
BSW	BSW_RAD_MASTER_A0080000		Non-equipped System or Communication Error		
BSW(SUB)	BSW_RAD_SLAVE_A0080000		Non-equipped System or Communication Error		

All DTCS

Setting	
Item	Information
M.U.T.-3 Version	SEW21121-00
V.C.I. Version	B179
Vehicle Information	DBA-GF7W 2019MY

Reg no: EK524
 After use MUT-3 ver. int. to ECU all the fault
 has been done by Q.C. Test drive.

2022.01.03
