



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



### ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SHENG YEE ZHER (SHENG YIZHE)  BLK 103 LENGKONG TIGA #12-379 SINGAPORE 410103  Contact No Mobile: 96956565	Cust No/Name	/SHENG YEE ZHER (SHENG YIZHE)
	Reg No/Reg Date	EK52H / 13/11/201
	Date In/Mileage	/ 0
	Chassis No	GF7W0600200
	Engine No	4J11AA4180
	Make/Model	MIT/19MY OUTLANDER 2.0 MODERN(995)
	Colour/Trim	U01 TITANIUM GREY M/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	22/12/2021/ 18:28	BLC	442 / CocoLu	19078

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW REAR BUMPER, REPAIR TAILGATE				900.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, TAILGATE				700.00
M SUNDRY Sundry				20.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				80.00
A 54900099 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
M FACE,RR BUMPER	1.00	1018.00	00.00	1018.00
M EXTENSION,RR BUMPER	1.00	292.00	00.00	292.00
M REINFORCEMENT,RR BUMPER,LH	1.00	79.00	00.00	79.00
M BRKT,R/BMPR FACE SIDE,LH	1.00	12.00	00.00	12.00
M MOULDING,RR BUMPER,LH	1.00	106.00	00.00	106.00
M LAMP ASSY,COMB,RR LH	1.00	603.00	00.00	603.00
M REFLECTOR,TAIL LAMP,LH	1.00	100.00	00.00	100.00
M LAMP ASSY,TAIL,LH	1.00	506.00	00.00	506.00

Confirm &amp; accepted by

	Nett	4,566.00
7% GST on	4566.00	319.62
Total Payable		4,885.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.