

**Team AutoPro Pte Ltd** 160 Sin Ming Drive #02-12 Autocity Singapore 575722

Tel: 8269-9999 Email: teamautopl@gmail.com / teamautooffice@gmail.com

SJE : \_\_\_\_\_  
 Date of Survey : \_\_\_\_\_  
 Date of ReSurvey: \_\_\_\_\_  
 Contacts : \_\_\_\_\_

Vehicle Nos : **SMQ 8543 D**  
 Model : Jaruar XF  
 Year : 2008  
 Chassis No : SAJAC05D89FR25841

**\* AGREED Cost Of Repair and Repair Day/s with SJE \***

Amount: \_\_\_\_\_ Working Day: \_\_\_\_\_

2008

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front fender RH	1	\$ 2,452.00	\$ <del>2,452.00</del> 2,452.00
2	Front fender outer garnish RH	1	\$ 359.60	\$ <del>359.60</del> 280.00
3	Front door RH	1	\$ 4,460.00	\$ <del>4,460.00</del> 1,336.00
4	Front door outer black garnish	1	\$ 485.00	\$ <del>485.00</del>
5	Front door outer handle	1	\$ 350.00	\$ 350.00
6	Front door weatherstrip	1	\$ 298.00	\$ <del>298.00</del>
7	Front door inner lock	1	\$ 415.00	\$ 415.00
8	Front door inner lock striker	1	\$ 88.00	\$ <del>88.00</del>
9	Front door inner trimboard	1	\$ 1,042.00	\$ <del>1,042.00</del>
10	Front door glass regulator	1	\$ 660.00	\$ <del>660.00</del> 593.70
11	Front door glass regulator motor	1	\$ 750.00	\$ <del>750.00</del> 299.00
12	Front door glass channel bracket	1	\$ 285.00	\$ <del>285.00</del>
13	Front door glass channel rubber	1	\$ 195.00	\$ <del>195.00</del>
14	Front door hinge	2	\$ 115.00	\$ <del>230.00</del>
15	Rear door RH	1	\$ 4,928.20	\$ 4,928.20
16	Side mirror assy RH	1	\$ 1,184.00	\$ <del>1,184.00</del> 969.70
17	Side mirror cover RH	1	\$ 410.00	\$ <del>410.00</del> 302.40
18	Side mirror glass RH	1	\$ 254.00	\$ <del>254.00</del> ✓254.00
19	Front lower arm RH	1	\$ 1,440.00	\$ <del>1,440.00</del>
20	Front upper arm RH	1	\$ 780.00	\$ <del>780.00</del>
21	Front shock absorber RH	1	\$ 1,182.00	\$ <del>1,182.00</del>
22	Front knuckle arm RH	1	\$ 1,669.70	\$ <del>1,669.70</del>
23	Front knuckle arm bearing RH	1	\$ 458.60	\$ <del>458.60</del>
Parts Sub Total :				\$ 5,284.80 24,376.10
Discount 10% :				\$ 528.48 2,437.61
PARTS TOTAL :				\$ 21,938.49

DDV  
 CUT ✓  
 DD ✓  
 BR ✓ NSX  
 CUT RX  
 NDX  
 NDX  
 NDX  
 NDX  
 NDX  
 BT ✓  
 SC ✓  
 NSX  
 NDX  
 NDX  
 CUT RX  
 BR ✓  
 BR ✓  
 BR ✓  
 } NDX

4756.32

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ <del>80.00</del>
2	Front fender sealant	1	\$ 100.00	\$ <del>100.00</del>
3	Front door sealant	1	\$ 100.00	\$ <del>100.00</del> 30.00
4	Front door speaker	1	\$ 210.00	\$ <del>210.00</del>
5	Front door inner trimboard clips	1	\$ 60.00	\$ <del>60.00</del>
6	Rear door sealant	1	\$ 100.00	\$ <del>100.00</del>
7	Front alloy rim	1	\$ 980.00	\$ <del>980.00</del>
8	Front tyre	1	\$ 480.00	\$ <del>480.00</del>
SPECIAL NETT TOTAL :				\$ 2,110.00

NNX  
 NNX  
 NEC ✓  
 NDX  
 NNX  
 NNX  
 NDX  
 NDX

Nos.	LABOUR		\$\$	
1	R&R front door component	\$	80.00	150.00 /
2	R&R rear door component	\$		150.00 NNX
3	R&R front under carriage	\$		300.00 NNX
4	R&R front tyre and balancing	\$		180.00 NNX
5	Wheel alignment	\$		180.00 NNX
6	Diagnostic reset fault code	\$	120.00	300.00 HEC ✓
7	Conduct water leak test	\$		180.00 NNX
8	Check wiring	\$		100.00 NNX
9	Upholstery	\$		300.00 NNX
10	Panel beating	\$	600.00	1,400.00 /
11	Rust proofing	\$		200.00 NNX
12	Spray painting	\$	600.00	1,400.00 /
LABOUR TOTAL :		\$		4,760.00

Survey 23/12/2021  
 ReSurvey 24/12/2021  
 TQRM lin 1240 hrs  
 TQRM lin 1120 hrs

LABOUR TOTAL : \$ 4,760.00  
 1400.00  
 PARTS TOTAL : \$ 21,938.49  
 SPECIAL NETT TOTAL : \$ 2,110.00  
 LABOUR TOTAL : \$ 4,760.00  
 GRAND TOTAL : \$ 28,808.49

Lump sum repair  
 Repair days 5

parts 4,756.32  
 SN 30.00  
 Labour 1,400.00  
 6,186.32  
 @ 20% 1,237.26  
 4,949.06

LS 4950/2

TQRM lin  
 25/12/2021

**LJK Auto Consultants** hence now,  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: