



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
RIAZ LLC 133 NEW BRIDGE ROAD #09-09 CHINATOWN POINT SINGAPORE 059413			Ref: CS/LAW21013047/Dqy3m4 Date: 31/08/2022 Code: L135	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SLT 2515X		Veh. Inspected	SJM 1666K
Policy No.			Coverage (\$)	0.00
Claim No.	WAN.IN.516660.J		Excess (\$)	0.00
Assign From	YA YEW KEE		Assign Date	22/12/2021
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY HYBRID		c.c	2487
Engine No.	HIDDEN		Year of Reg.	2018
Chassis No.	AXVH701023173		Colour	WHITE
Odometer	57642 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	SPORTS RIM
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 R17	MICHELIN	5 mm
	L/H Front Tyre	215/55 R17	MICHELIN	5 mm
	R/H Rear Tyre	215/55 R17	MICHELIN	5 mm
	L/H Rear Tyre	215/55 R17	MICHELIN	5 mm
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
	Accident Date	09/10/2020	Inspection Date	15/07/2022
	Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	