



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
TAN CHIN HOE & CO 24 RAFFLES PLACE #24-01 CLIFFORD CENTRESINGAPORE 048621			Ref: CS/LAW21013047/Dqy3m4	
			Date: 31/08/2022	
			Code: L128	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	SLT 2515X	Veh. Inspected	SJM 1666K	
Policy No.		Coverage (\$)	0.00	
Claim No.	RT/CC/429/2021/yk	Excess (\$)	0.00	
Assign From	YA YEW KEE	Assign Date	22/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA CAMRY HYBRID	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	AXVH701023173	Colour	WHITE	
Odometer	57642 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	MICHELIN	5 mm	
L/H Front Tyre	215/55 R17	MICHELIN	5 mm	
R/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
L/H Rear Tyre	215/55 R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	09/10/2020	Inspection Date	15/07/2022	
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	