

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1035/2021/JT
DATE : 21-Dec-21
WIP : 59406

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR ZHOU MENG
ADDRESS : 167 JALAN JURONG KECHIL
#07-04
SINGAPORE 598671
TELEPHONE : HP +65 97809711
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900021928-01
VEHICLE NO : **SJP 6004 Y**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 25/2/2019
ENGINE NO : CHZ C26224
CHASSIS NO : WAUZZZ8V6K1014173
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Dec-21
PLACE OF ACCIDENT : AYE TOWARDS TUAS AFTER
BUONA VISTA

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJP 6004 T

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00 X	
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00 X	
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 1,050.00 500 ✓	
4	TO RESPRAY FRONT BUMPER.	\$ 900.00 550 ✓	
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>2,852.00</u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJP 6004 Y

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	1	\$ 1,987.00	+
2	FRONT BUMPER FIXING PARTS	1	\$ 187.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>} Men</i>	1	\$ 39.00	+
4	FRONT BUMPER GRILLE - CENTER	1	\$ 160.00	+
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>Men</i>	1	\$ 536.00	+
6	FRONT BUMPER CLOSING ELEMENT - RH <i>Men</i>	1	\$ 297.00	+
7	FRONT BUMPER TRIM COVER - RH <i>} Men</i>	1	\$ 163.00	+
8	FRONT WHEEL HOUSING LINER ADAPTER - RH <i>} Men</i>	1	\$ 38.00	+
9	RADIATOR GRILLE <i>Can't</i>	1	\$ 1,406.00	✓ 1124.8
10	RADIATOR GRILLE CLOSING ELEMENT <i>?</i>	1	\$ 191.00	?
11	SIGN "CAUTION" <i>} Men</i>	1	\$ 14.00	✓ 10.88
12	AIR COND STICKER	1	\$ 8.00	✓ 5.68
13	FRONT BUMPER FOAM FILLER PIECE <i>?</i>	1	\$ 189.00	?
14	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?</i>	1	\$ 122.00	?
15	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	1	\$ 795.00	?
16	HORN LOW TONE - RH <i>Men</i>	1	\$ 200.00	+
17	RADIATOR AIR GUIDE - RH <i>} Men</i>	1	\$ 25.00	+
18	RADIATOR SEAL OUTER - RH <i>} Men</i>	1	\$ 8.00	+
19	RADIATOR AIR GUIDE UPPER - CENTER <i>Men</i>	1	\$ 12.00	+
20	HEADLIGHT - RH <i>Men</i>	1	\$ 5,455.00	+
21	HEADLIGHT WASHER ASSY - RH <i>} Men</i>	1	\$ 142.00	+
22	LIFT CYLINDER HOSE	1	\$ 68.00	+
23	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓ 60
24	SUNDRIES <i>?</i>	1	\$ 200.00	?
TOTAL SPARE PARTS		:	\$ 12,302.00	
TOTAL LABOUR CHARGES		:	\$ 2,852.00	
GRAND TOTAL		:	\$ 15,154.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

:

Adrian L

SURVEYED DATE

:

22/12/21.

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

:

Not Authorised, 03 days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT