

55 UBI ROAD 1 SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL NOFA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1031/2021/JT
DATE : 21-Dec-21
WIP : 59394

Xiao Chen.

\$7609.36.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS LIU YI
ADDRESS : 27 OXLEY WALK
#02-25
SINGAPORE 238596
TELEPHONE : HP +65 93377880
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1700070654-04
VEHICLE NO : SLT 4377 P
MODEL CODE : AUDI S5 SB 3.0 TFSI
MODEL YEAR : 28/10/2017
ENGINE NO : CWG 042893
CHASSIS NO : WAUZZZF50JA037465
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Dec-21
PLACE OF ACCIDENT : CTE TOWARDS BUYONG ROAD
ENTRANCE



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6341 1183

EMAIL: NORA.KHAIR@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLT 4377 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	✓
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,400.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,200.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,672.00	



PREMIUM AUTOMOBILES




85 UBI ROAD, SINGAPORE 408590
TEL: 6396 2323 FAX: 6341 1193

EMAIL: INQUIRY@PREMIUMAUTO.COM.SG CLAIM@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SML 7240 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER Repair Torn	1	\$ 2,941.00	✓	2352.80
2	FRONT BUMPER FIXING PARTS	1	\$ 407.00	✓	
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00	✓	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 511.00	✓	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 228.00	✓	
6	FRONT BUMPER AIR GUIDE - LH / RH	2	\$ 126.00	✓	
7	RADIATOR GRILLE	1	\$ 3,508.00	✓	2806.40
8	FRONT PARKING AID SENSOR SUPPORT - LH / RH	2	\$ 102.00	✓	
9	RADIATOR GRILLE UPPER COVER	1	\$ 189.00	✓	
10	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 736.00	✓	
11	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	?	×
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 845.00	✓	
13	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 72.00	✓	
14	FRONT BUMPER TOP COVER	1	\$ 127.00	✓	101.60
15	"CAUTION" STICKER	1	\$ 14.00	✓	10.88
16	AIR COND STICKER	1	\$ 8.00	✓	5.68
17	FRONT LOCK CARRIER BRACKET	1	\$ 137.00	?	×
18	FRONT LOCK CARRIER SUPPORT - LH / RH	2	\$ 58.00	?	×
19	POP RIVET	4	\$ 4.00	?	×
20	HORN - RH	1	\$ 126.00	✓	
SUB TOTAL SPARE PARTS			\$ 10,334.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1 SINGAPORE 408699

TEL: 6386 2323 FAX: 6343 1193

EMAIL: NURA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLT 4377 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	HORN BRACKET - RH <i>all m</i>	1	\$ 29.00	✓	
22	FRONT PARKING AID SENSOR - INNER / OUTER <i>all m</i>	2	TBC	✓	
23	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	✓	
24	BONNET <i>Repair</i>	1	\$ 3,312.00	✓	
25	BONNET IMPACT PROTECTION - CENTER / LH / RH <i>all m</i>	3	\$ 84.00	✓	
26	BONNET STRIKER - RH <i>all m</i>	1	\$ 50.00	✓	
27	BONNET LOCK	1	\$ 214.00	✓	
28	HEADLIGHT - RH <i>all m</i>	1	\$ 7,902.00	✓	
29	LIFT CYLINDER - RH	1	\$ 198.00	✓	
30	LIFT CYLINDER CORRUGATED PIPE	1	\$ 86.00	✓	
31	RADIATOR AIR GUIDE RH - INNER / OUTER <i>all m</i>	2	\$ 47.00	✓	
32	RADIATOR AIR GUIDE UPPER	1	\$ 16.00	✓	
33	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓✓	
34	SUNDRIES <i>all m</i>		\$ 300.00	✓	
TOTAL SPARE PARTS		:	\$ 22,641.00		
TOTAL LABOUR CHARGES		:	\$ 5,672.00		
GRAND TOTAL		:	\$ 28,313.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6341 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

NAME

Adrian Lg

SURVEYED DATE

22/12/21

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Not Authorised, 04 Days
H.S.

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT