



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1034/2021/JT
DATE : 21-Dec-21
WIP : 59365

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR JASON SAMUEL WILLIAMS
ADDRESS : 57 COVE WAY
#03-04
SINGAPORE 098308
TELEPHONE : HP +65 85681253
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070152652
VEHICLE NO : **SMV 9866 P**
MODEL CODE : AUDI Q3 1. TFSI S TRONIC
MODEL YEAR : 29/10/2020
ENGINE NO : CZD C06646
CHASSIS NO : WAUZZZF30M1012858
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Dec-21
PLACE OF ACCIDENT : INTERSECTION OF WOODLANDS AVE
1 & WOODLANDS AVE 6

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9866 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓
2	TO REMOVE AND TRANSFER HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500
4	TO RESPRAY FRONT BUMPER AND FRONT FENDER. X	\$ 2,000.00	550
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 4,672.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9866 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER <i>torn</i>	1	\$ 1,008.00	✓	
2	FRONT BUMPER CONNECTING PIECE <i>new</i>	1	\$ 145.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LH <i>new</i>	1	\$ 59.00	+	
4	FRONT BUMPER GRILLE - CENTER ?	1	\$ 217.00	?	
5	FRONT BUMPER GRILLE LOWER COVER ?	1	\$ 51.00	?	
6	FRONT BUMPER GUIDE <i>new</i>	1	\$ 110.00	+	
7	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 190.00	+	
8	FRONT BUMPER SPOILER <i>at</i>	1	\$ 383.00	✓	
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	1	\$ 153.00	+	
10	FRONT BUMPER BRACKET <i>new</i>	1	\$ 21.00	+	
11	RADIATOR GRILLE <i>could</i>	1	\$ 1,433.00	✓	
12	RADIATOR STRIKER PLATE ?	1	\$ 244.00	?	
13	RADIATOR GRILLE COVER ?	1	\$ 45.00	?	
14	RADIATOR BRACKET ?	1	\$ 41.00	?	
15	FRONT CAMERA ?	1	\$ 1,141.00	?	
16	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 102.00	?	
17	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 916.00	?	
18	FRONT BUMPER GUIDE SECTION - LH <i>new</i>	1	\$ 39.00	+	
19	FRONT BUMPER TOP COVER <i>new</i> ?	1	\$ 123.00	+	?
20	SIGN " CAUTION " <i>new</i> ?	1	\$ 14.00	+	?
SUB TOTAL SPARE PARTS		:	\$ 6,435.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9866 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR CON STICKER ?	1	\$ 8.00	* ?
22	HORN - HIGH TONE LH } ?	1	\$ 137.00	+
23	HORN BRACKET - LH } ?	1	\$ 22.00	+
24	FRONT PARKING AID SENSOR	2	TBC	+
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	+
26	FRONT BUMPER WIRING SET } ?	1	\$ 676.00	+
27	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	+
28	FRONT WHEEL HOUSING LINER ATTACHEMENTS PARTS } ?	1	\$ 101.00	+
29	FRONT FENDER TOP COVER - LH } ?	1	\$ 16.00	+
30	HEADLIGHT MOUNTING } ?	1	\$ 118.00	+
31	HEADLIGHT - LH He Not Consistent	1	\$ 5,589.00	X
32	LIFT CYLINDER - LH He	1	\$ 210.00	+
33	HEADLIGHT HOSE He	1	\$ 80.00	+
34	FRONT WHEEL ARCH COVER - LH / RH He	2	\$ 536.00	—
35	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$ 7.00	?
36	HEADLIGHT MOUNTING - RH He	1	\$ 118.00	+
37	FRONT NO PLATE Dented	S/N	\$ 60.00	✓
38	SUNDRIES ?		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 14,612.00	
TOTAL LABOUR CHARGES		:	\$ 4,672.00	
GRAND TOTAL		:	\$ 19,284.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lim*
SURVEYED DATE : *22/12/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT