

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1034/2021/JT
DATE : 21-Dec-21
WIP : 59365

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 22/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

4 days - ok - Jy - 13 Apr 22

OWNER'S NAME : MR JASON SAMUEL WILLIAMS
ADDRESS : 57 COVE WAY
#03-04
SINGAPORE 098308
TELEPHONE : HP +65 85681253
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070152652
VEHICLE NO : **SMV 9866 P**
MODEL CODE : AUDI Q3 1. TFSI S TRONIC
MODEL YEAR : 29/10/2020
ENGINE NO : CZD C06646
CHASSIS NO : WAUZZZF30M1012858
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Dec-21
PLACE OF ACCIDENT : INTERSECTION OF WOODLANDS AVE
1 & WOODLANDS AVE 6

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9866 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR , HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00		
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. TO REPAIR LHS FRONT FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND FRONT FENDER.	\$	2,000.00	\$	550.00
5	SUPPLEMENTARY	\$	1,400.00	\$	1,400.00
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 6,072.00	\$	3,122.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9866 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 1,008.00	\$ 806.40
2	FRONT BUMPER CONNECTING PIECE	1	\$ 145.00	
3	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 59.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 217.00	\$ 173.20
5	FRONT BUMPER GRILLE LOWER COVER	1	\$ 51.00	
6	FRONT BUMPER GUIDE	1	\$ 110.00	\$ 98.80
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 190.00	
8	FRONT BUMPER SPOILER	1	\$ 383.00	\$ 306.40
9	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 153.00	
10	FRONT BUMPER BRACKET	1	\$ 21.00	
11	RADIATOR GRILLE	1	\$ 1,433.00	\$ 1,146.40
12	RADIATOR STRIKER PLATE	1	\$ 244.00	\$ 194.80
13	RADIATOR GRILLE COVER	1	\$ 45.00	
14	RADIATOR BRACKET	1	\$ 41.00	
15	FRONT CAMERA	1	\$ 1,141.00	
16	FRONT BUMPER FOAM FILLER PIECE	1	\$ 102.00	
17	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 916.00	
18	FRONT BUMPER GUIDE SECTION - LH	1	\$ 39.00	
19	FRONT BUMPER TOP COVER	1	\$ 123.00	\$ 98.00
20	SIGN " CAUTION "	1	\$ 14.00	\$ 10.88
SUB TOTAL SPARE PARTS		:	\$ 6,435.00	\$ 2,834.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9866 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	2,834.88
21	AIR CON STICKER	1	\$ 8.00	\$	5.68
22	HORN - HIGH TONE LH	1	\$ 137.00		
23	HORN BRACKET - LH	1	\$ 22.00		
24	FRONT PARKING AID SENSOR	2	TBC		
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00		
26	FRONT BUMPER WIRING SET	1	\$ 676.00		
27	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00		
28	FRONT WHEEL HOUSING LINER ATTACHEMENTS PARTS	1	\$ 101.00		
29	FRONT FENDER TOP COVER - LH	1	\$ 16.00		
30	HEADLIGHT MOUNTING	1	\$ 118.00	\$	94.40
31	HEADLIGHT - LH	1	\$ 5,589.00		
32	LIFT CYLINDER - LH	1	\$ 210.00		
33	HEADLIGHT HOSE	1	\$ 80.00		
34	FRONT WHEEL ARCH COVER - LH / RH	2	\$ 536.00	\$	428.80
35	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00		
36	HEADLIGHT MOUNTING - RH	1	\$ 118.00	\$	94.40
37	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
38	SUPPLEMENTARY		\$ 691.00	\$	551.76
40	SUNDRIES		\$ 250.00	\$	18.00
TOTAL SPARE PARTS			\$ 15,303.00	\$	4,087.92
TOTAL LABOUR CHARGES			\$ 6,072.00	\$	3,122.00
GRAND TOTAL			\$ 21,375.00	\$	7,209.92

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-23/02/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1034/2021/JT

10-Feb-22

CHANG

1 of 1

SMV 9866 P

AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

Labours

1	TO REMOVE AND RENEW AIRCON CONDENSER. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,400.00	\$ 1,400.00
---	---	-----------------	-------------

Parts

1	RADIATOR AIR GUIDE - LH/RH	2	\$ 86.00	\$ 68.16
2	A/C CONDENSER	1	\$ 605.00	\$ 483.60

GRAND TOTAL \$ **2,091.00** \$ **1,951.76**

For Premium Automobiles Pte Ltd

 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT