

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Xiao Chan.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/1034/2021/JT
10-Feb-22
CHANG
1 of 1
SMV 9866 P
AUDI Q3 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO REMOVE AND RENEW AIRCON CONDENSER. TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$ 1,400.00	
Parts			
1	RADIATOR AIR GUIDE - LH/RH <i>checked</i>	\$ 86.00	<i>ll.s.</i>
2	A/C CONDENSER <i>Replaced</i>	\$ 605.00	<i>ll.s.</i>
GRAND TOTAL			\$ 2,091.00

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling.
ll.s. 10/02/22.

Add 1 day for the replacement
of air con condensers.

Car-in

9/2/22

wip: 59365
Kiam /

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6341 1183
EMAIL: NGRA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


Azi- Adrian
- 3 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9869 P

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER Torn	1	\$ 1,008.00	✓	
2	FRONT BUMPER CONNECTING PIECE new	1	\$ 145.00	+	
3	FRONT BUMPER CLOSING ELEMENT - LH new	1	\$ 59.00	+	
4	FRONT BUMPER GRILLE - CENTER Behind	1	\$ 217.00	✓	sls.
5	FRONT BUMPER GRILLE LOWER COVER	1	\$ 51.00	✓	
6	FRONT BUMPER GUIDE Damaged	1	\$ 110.00	✓	sls.
7	FRONT BUMPER CLOSING ELEMENT new	1	\$ 190.00	+	
8	FRONT BUMPER SPOILER at	1	\$ 383.00	✓	
9	FRONT BUMPER AIR GUIDE GRILLE - LH new	1	\$ 153.00	+	
10	FRONT BUMPER BRACKET new	1	\$ 21.00	+	
11	RADIATOR GRILLE could	1	\$ 1,433.00	✓	sls.
12	RADIATOR STRIKER PLATE Embedded	1	\$ 244.00	✓	sls.
13	RADIATOR GRILLE COVER ?	1	\$ 45.00	?	
14	RADIATOR BRACKET ?	1	\$ 41.00	?	
15	FRONT CAMERA ?	1	\$ 1,141.00	?	
16	FRONT BUMPER FOAM FILLER PIECE ?	1	\$ 102.00	?	
17	FRONT BUMPER REINFORCEMENT BEAM ?	1	\$ 916.00	?	
18	FRONT BUMPER GUIDE SECTION - LH new	1	\$ 39.00	+	
19	FRONT BUMPER TOP COVER new could	1	\$ 123.00	✓	sls.
20	SIGN " CAUTION " new new	1	\$ 14.00	✓	sls.
SUB TOTAL SPARE PARTS		:	\$ 6,435.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORE.KHIA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9866 P

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	AIR CON STICKER <i>2 New</i>	1	\$ 8.00	*	<i>2</i>
22	HORN - HIGH TONE LH <i>2 New</i>	1	\$ 137.00	+	
23	HORN BRACKET - LH	1	\$ 22.00	+	
24	FRONT PARKING AID SENSOR	2	TBC	+	
25	FRONT PARKING AID SENSOR SEAL RING	4	\$ 9.00	+	
26	FRONT BUMPER WIRING SET	1	\$ 676.00	+	
27	FRONT WHEEL HOUSING LINER - LH	1	\$ 240.00	+	
28	FRONT WHEEL HOUSING LINER ATTACHEMENTS PARTS <i>New</i>	1	\$ 101.00	+	
29	FRONT FENDER TOP COVER - LH <i>New</i>	1	\$ 16.00	+	
30	HEADLIGHT MOUNTING <i>Cracked</i>	1	\$ 118.00	+	
31	HEADLIGHT - LH <i>New Not Consistent</i>	1	\$ 5,589.00	X	
32	LIFT CYLINDER - LH <i>New</i>	1	\$ 210.00	+	
33	HEADLIGHT HOSE <i>New</i>	1	\$ 80.00	+	
34	FRONT WHEEL ARCH COVER - LH / RH <i>New</i>	2	\$ 536.00	—	
35	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 7.00	?	
36	HEADLIGHT MOUNTING - RH <i>Cracked</i>	1	\$ 118.00	+	
37	FRONT NO PLATE <i>Dented</i>	S/N	\$ 60.00	✓	
38	SUNDRIES		\$ 250.00	?	
TOTAL SPARE PARTS			:	\$ 14,612.00	
TOTAL LABOUR CHARGES			:	\$ 4,672.00	
GRAND TOTAL			:	\$ 19,284.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.