



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21013058/Uvf3n2	
			Date: 14/01/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	XE 945M	Veh. Inspected	SLR 590B
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2103788/LOR	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	23/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	VOLKSWAGEN GOLF A7 (A)	c.c	1395
	Engine No.	HIDDEN	Year of Reg.	2013
	Chassis No.	WVWZZZAUZEW057943	Colour	SILVER
	Odometer	71852 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
	R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
	L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/12/2021	Inspection Date	27/12/2021
	Survey held at	MILLION AUTO SERVICE 4 PENJURU PLACE #01-12 2.8 PENJURU TECH HUP SINGAPORE 608782		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	