

Our Ref: SDN8212G

Your Ref: FBQ7101H

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR TAILGATE		REPAIR
2	1	REAR TAILGATE LOGO MITSUBISHI		\$ <i>RE</i> 117.70
3	1	REAR TAILGATE EMBLEM ASX		\$ <i>RE</i> 93.80
4	1	REAR BUMPER <i>838</i>		\$ <i>Bu</i> 1,604.50
5	1	REAR BUMPER CENTRE COVER		\$ <i>RE</i> 217.50
6	1	REAR BUMPER INNER LOWER BRACKET RH		\$ <i>RE</i> 53.00
7	1	REAR BUMPER INNER LOWER BRACKET LH		\$ <i>RE</i> 53.00
8	1	REAR BUMPER REINFORCEMENT		\$ <i>RE</i> 589.20
9	1	REAR END PANEL		REPAIR
			SUB TOTAL	\$ 2,728.70
			LESS 10%	\$ 272.87
			TOTAL AMOUNT	\$ 2,455.83

Our Ref: SDN8212G

Your Ref: FBQ7101H

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR TAILGATE EMBLEM C&C		\$ <i>RE</i> 50.00
2	1	REAR BUMPER CLIPS		\$ <i>RE</i> 60.00
3	1 SET	REAR BUMPER REVERSE SENSORS		\$ <i>RE</i> 250.00
			SUB TOTAL	\$ 360.00
			TOTAL PARTS COST	\$ 2,815.83

11 Lys @ 1550/h

3 days

