



**Auto Insure Pte. Ltd.**  
6 Marsiling Lane  
Singapore (739145)  
E: claims01@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
**GST No.: 201437380M**

**Page No.1**

**AUTOMOBILE ASSESSMENT REPORT**

Our Ref: **SDN8212G (SIEW)**

Your Ref: **FBQ7101H**

Date: **23-Dec-21**

BY EMAIL ONLY  
(claims01@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

**SOMPO INSURANCE SINGAPORE PTE LTD**

50 RAFFLES PLACE,  
#03-03 SINGAPORE LAND TOWER,  
SINGAPORE : 048623

Assessed Vehicle No : **SDN8212G**  
Car Make and Model : **MITSUBISHI ASX 2.0 CVT ABS D/AIRBAG 2WD**  
Date of Accident : **25-Nov-21**  
Date of Assessment : **23-Dec-21**

We have carried out a physical assessment of SDN8212G at our workshop Auto Insure Pte Ltd sustained damages to the REAR portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the REAR portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : **L/S**  
Adjusted Amount : **\$ 5,000.00**  
Est. Repair Days : **4**



Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a "**WITHOUT PREJUDICE**" basis.  
If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**  
This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.  
No liability or responsibility whatsoever shall be held by  
**AUTO INSURE PTE. LTD.** For any reliance on this report by any third party.

Our Ref: SDN8212G

Your Ref: FBQ7101H

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR TAILGATE		REPAIR
2	1	REAR TAILGATE LOGO MITSUBISHI		\$ 117.70
3	1	REAR TAILGATE EMBLEM ASX		\$ 93.80
4	1	REAR BUMPER 838		\$ 1,604.50
5	1	REAR BUMPER CENTRE COVER		\$ 217.50
6	1	REAR BUMPER INNER LOWER BRACKET RH		\$ 53.00
7	1	REAR BUMPER INNER LOWER BRACKET LH		\$ 53.00
8	1	REAR BUMPER REINFORCEMENT		\$ 589.20
9	1	REAR END PANEL		REPAIR
			SUB TOTAL	\$ 2,728.70
			LESS 10%	\$ 272.87
			TOTAL AMOUNT	\$ 2,455.83

Our Ref: SDN8212G

Your Ref: FBQ7101H

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR TAILGATE EMBLEM C&C		\$ 50.00
2	1	REAR BUMPER CLIPS		\$ 60.00
3	1 SET	REAR BUMPER REVERSE SENSORS		\$ 250.00
			SUB TOTAL	\$ 360.00
			TOTAL PARTS COST	\$ 2,815.83

Our Ref: SDN8212G

Your Ref: FBQ7101H

S/NO	DESCRIPTION	EST. BY WORKSHOP	
	<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ 600.00	400h
2	TO REMOVE & REFIT WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ 120.00	15h
3	TO CONDUCT DIGNOSIS FAULT CODE & RESET	\$ nn 150.00	X
4	TO REMOVE & REFIT REAR BUMPER REVERSE SENSORS	\$ 100.00	50h
5	TO REMOVE & REFIT UPHOLSTERY GARNISH AND ATTACHMENT PARTS	\$ nn 120.00	X
7	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ 600.00	440h
8	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ nn 50.00	X
9	SUNDRIES (SAND PAPER, WELDING WIRE ETC.)	\$ nn 50.00	X
10	TO VACUUM, WAXING & CLEAN	\$ nn 50.00	X
11	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ nn 50.00	X
TOTAL BEFORE GST		\$ 4,705.83	
GST 7%		\$ 329.41	
TOTAL (PARTS & LABOUR):		\$ 5,035.24	

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$ 5,000.00 for lump sum with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director