

**Note: This document has not been finalised.**

# **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 30 Dec 2021

## **Preliminary Advice**

Vehicle No	: SNB8727H	Accident Date	: 18/12/2021
Make	: TOYOTA YARIS CROSS	Policy No.	: DMPCSNW00190802100
Assignment Date	: 22/12/2021	Excess	: S\$0.00
Date of Inspection	: 28/12/2021	Est. Duration of Repair	: 4
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,580.86
Revised Amount	:S\$	6,080.86
Check Items (Estimated)	:S\$	1,305.00
Total	:S\$	7,385.86

Lump Sum Repair :S\$

## **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$ 102,000.00
COE / PARF Rebate	:S\$ 43,785.00

Salvage Value	:S\$
Margin for Repair	:S\$ 58,215.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.