

Ding Auto Pte Ltd (Co.Reg.No:201311788Z)

176 Sin Ming Drive #04-06, Sin Ming Autocare

Singapore 575721

Tel: 64521208 Fax: 64520614 Email: ding@dingauto.sg;kenneth.ding@dingauto.sg

(SUPPLEMENTARY)

INSURER: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPCSNW00190802100	Date of Loss:	18/12/2021
Vehicle Reg. No.:	SNB8727H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ONG KAY SOON LIGHTZ		
Driver:	ONG KAY SOON LIGHTZ		
Make/Model:	TOYOTA YARIS CROSS, 1.5 X B-PKG CVT (A)	Vehicle Reg. Date:	17/09/2021
Vehicle Colour:	RED		
Engine No:	M15AY181561	Chassis No:	MXPB102010218
Odometer:	3621 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	DING AUTO PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	250.00
Miscellaneous Items	0.00
Labour	500.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	750.00
+ GST 7.00% (S\$)	52.50
Nett Amount (S\$)	802.50
+ Previous Estimates (S\$)	8,111.52
Claim Total (S\$)	8,914.02

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2022)

Parts: M1-SUV TOYOTA YARIS CROSS 1.5 X B-PKG CVT (A)
(Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Ding Auto Pte Ltd/SNB8727H/19/04/2022 17:49

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*FRONT BUMPER LOWER GARNISH	mtg cracked	0.00	0.00	*250.00 F
F=Franchise part.							
Total Parts (S\$)							250.00

Ding Auto Pte Ltd/SNB8727H/19/04/2022 17:49. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	RADAR SENSOR - RESETTING	New 250	500.00
Gross Labour Cost (S\$)			500.00

Ding Auto Pte Ltd/SNB8727H/19/04/2022 17:49. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >