

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:jlperfectautowork@gmail.com



PERFECT
AUTOWORK
PTE LTD

Cecilia.

DATE : 23.12.2021

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SNC7433G**
MODEL : **TOYOTA YARIS CROSS**
DATE OF ACCIDENT : 22.12.2021
TIME OF ACCIDENT : 12:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER (UPPER) <i>3 Deformed</i>	1	\$ 485.40	\$ 485.40
2	REAR BUMPER (LOWER)	1	\$ 498.10	\$ 498.10
3	REAR BUMPER REFLECTOR <i>Not Nec</i>	2	\$ 110.30	\$ 220.60
4	REAR BUMPER TOW HOOK COVER <i>Not Nec</i>	1	\$ 76.00	\$ 76.00
5	REAR BUMPER LOWER CENTRE GARNISH <i>Not Nec</i>	1	\$ 498.00	\$ 498.00
6	REAR BUMPER REINFORCEMENT <i>Not Nec</i>	1	\$ 497.00	\$ 497.00
7	REAR BUMPER SIDE BRACKET <i>Not Nec</i>	2	\$ 103.60	\$ 207.20
8	REAR BUMPER SIDE RETAINER <i>Nec</i>	2	\$ 98.30	\$ 196.60
9	TAILGATE <i>Dented.</i>	1	\$ 1,280.10	\$ 1,280.10
10	TAILGATE REFLECTOR <i>2</i>	2	\$ 196.70	\$ 393.40
11	TAILGATE LAMP <i>Not Nec</i>	2	\$ 331.60	\$ 663.20
12	TAILGATE CENTER REFLECTOR	1	\$ 211.60	\$ 211.60
13	TAILGATE DAMPER <i>Not Nec</i>	2	\$ 211.50	\$ 423.00
14	TAILGATE INNER HOLDER <i>Not Nec</i>	1	\$ 69.30	\$ 69.30
15	TAIL GATE LOGO <i>2</i>	1	\$ 81.70	\$ 81.70
16	TAILGATE EMBLEM 'YARIS' <i>Not Nec</i>	1	\$ 98.70	\$ 98.70
17	TAILGATE EMBLEM 'CROSS'	1	\$ 93.30	\$ 93.30
18	TAILGATE STOPPER <i>Not Nec</i>	2	\$ 38.10	\$ 76.20
19	TAILGATE TOP LOCK <i>Damaged</i>	1	\$ 268.10	\$ 268.10
20	TAILGATE LOWER LOCK <i>Not Nec</i>	1	\$ 68.00	\$ 68.00
21	TAILGATE INNER TRIM <i>Not Nec</i>	1	\$ 651.30	\$ 651.30
22	TAILGATE WEATHER STRIP <i>Not Nec</i>	1	\$ 285.70	\$ 285.70
23	TAILGATE WINDSCREEN MOULDING (SET) <i>Not Nec</i>	1	\$ 191.30	\$ 191.30
24	TAIL LAMP <i>LVA Combined</i>	2	\$ 495.30	\$ 990.60
25	TAIL LAMP LOWER BRACKET <i>Not Nec</i>	2	\$ 48.30	\$ 96.60

345

X-2 495.30

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SNC7433G
 MODEL : TOYOTA YARIS CROSS
 DATE OF ACCIDENT : 22.12.2021
 TIME OF ACCIDENT : 12:45HRS

26	REAR FENDER INNER TRIM <i>cracked.</i>	2	\$ 511.30	\$ 1,022.60	✓
27	REAR FENDER COWLING <i>Not Nec</i>	2	\$ 126.70	\$ 253.40	+
28	REAR FENDER ARCED GARNISH <i>Not Nec</i>	2	\$ 281.60	\$ 563.20	281.60
29	BLIND SPOT MONITOR <i>2 per</i>	2	\$ 1,582.00	\$ 3,164.00	+
30	BLIND SPOT MONITOR BRACKET <i>1 per</i>	2	\$ 347.00	\$ 694.00	+
31	REAR END PANEL <i>Dented</i>	1	\$ 516.40	\$ 516.40	✓
32	REAR END PANEL TOP GARNISH <i>Dented</i>	1	\$ 516.40	\$ 516.40	285
33	REAR FLOOR PANEL <i>Buckled.</i>	1	\$ 865.70	\$ 865.70	✓
34	REAR FLOOR PANEL CENTRE SPONGE <i>crack</i>	1	\$ 217.60	\$ 217.60	✓
35	REAR FLOOR PANEL TOP BOARD <i>Dented</i>	1	\$ 317.60	\$ 317.60	✓
36	REAR TOOLS SPONGE <i>Not in</i>	2	\$ 167.40	\$ 334.80	+
37	REVERSE SENSOR <i>Damaged</i>	2	\$ 223.60	\$ 447.20	✓
38	REVERSE SENSOR HOLDER <i>Not in</i>	2	\$ 67.00	\$ 134.00	+
39	REVERSE SENSOR WIRE HARNESS <i>Not in</i>	1	\$ 476.80	\$ 476.80	+

TOTAL PRICE \$ 18,144.70
 LESS 25% \$ 4,536.18
 SUB TOTAL PRICE \$ 13,608.53

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not Nec</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER LOWER CENTRE GARNISH CLIP (SET) <i>Not in</i>	1	\$ 50.00	\$ 50.00	20
4	REAR BUMPER REFLECTOR GARNISH CLIP (SE) <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
5	REAR SPOILER CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	+
6	TAIL LAMP CLIP (SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	10
7	TAILGATE SEALANT <i>Not in</i>	1	\$ 150.00	\$ 150.00	+
8	TAILGATE OUTER GARNISH CLIP (SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	+
9	TAILGATE INNER TRIM BOARD CLIP (SET) <i>Not in</i>	1	\$ 50.00	\$ 50.00	30
10	TAILGATE WINDSCREEN SEALANT <i>2 per</i>	1	\$ 80.00	\$ 80.00	40
11	TAILGATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	30
12	REAR FENDER INNER TRIM CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	60
13	REAR FENDER COWLING CLIP (SET) <i>Not in</i>	1	\$ 80.00	\$ 80.00	+
14	REAR FENDER ARCED GARNISH CLIP (SET) <i>Not in</i>	1	\$ 50.00	\$ 50.00	+
15	REAR END PANEL TOP GARNISH CLIPS (SET) <i>Not in</i>	1	\$ 30.00	\$ 30.00	10
16	REAR END PANEL INSULATION SEAL <i>Not in</i>	1	\$ 150.00	\$ 150.00	60
17	REAR FLOOR PANEL INSULATION SEAL <i>Not in</i>	1	\$ 150.00	\$ 150.00	60
18	REVERSE CAMERA <i>Not in</i>	1	\$ 450.00	\$ 450.00	+

TOTAL \$ 1,700.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SNC7433G**
 MODEL : **TOYOTA YARIS CROSS**
 DATE OF ACCIDENT : 22.12.2021
 TIME OF ACCIDENT : 12:45HRS

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00	1250
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	800
3	TUFF COAT	\$ 350.00	80
4	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80
5	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
7	REAR CHASSIS ALIGNMENT	\$ 180.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	TRANSFER TAILGATE MECHANISM	\$ 150.00	80
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
11	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 120.00	X
12	SPECAIL COATING	\$ 1,800.00	500
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00	X

TOTAL \$ 7,260.00

TOTAL PARTS COST : \$ 1,700.00
 TOTAL LABOUR COST : \$ 7,260.00
 TOTAL REPAIR COST : \$ 8,960.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

total: 9787.15

H/S: 7.8K

09 Days

(7.8K)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: