

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013065/ATY3N2**Date:** 26/04/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00004192100

Claimant Vehicle No : SLU8722U **Insured Vehicle No :** SLD1807U

Date of Loss: 17/12/2021 Nature of Claim: TP Claim No: SNM21D207473/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLU8722U**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: HIDDEN

Reg. Date: 01/12/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU593310

Colour: Silver Odometer: 103242 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16

Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,115.36	4,442.80	12,672.56	74.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,480.00	2,250.00	3,230.00	58.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,595.36	6,692.80	15,902.56	70.38
Approved Total (Overridden) (S\$)		5,300.00		
Nett Amount (S\$)	22,595.36	5,300.00	17,295.36	76.54

INSPECTION

Date of Assignment: 22/12/2021

Date Inspected: 23/12/2021 Inspected At: SR AUTOWORKS PTE LTD
8 KAKI BUKIT AVENUE 4, #02-24, PREMIER
@ KAKI BUKIT, SINGAPORE 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 26 Apr 2022)**Parts:** 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLU8722U)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR RH	Dented	1,904.70 FL	*1,782.00 FL
2	2		*FRONT DOOR RH BLACK STICKER RH	Necessary	90.00 FL	*50.00 FL
3	1		*FRONT DOOR CHROME MOULDING RH	Not Necessary	180.80 FL	*- FL
4	1		*FRONT DOOR INNER LOCK RH	Not Necessary	589.00 FL	*- FL
5	1		*FRONT DOOR LOCK CATCH LRH	Not Necessary	46.00 FL	*- FL
6	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	189.00 FL	*- FL
7	1		*FRONT DOOR INNER TRIM RH	Not Necessary	1,217.50 FL	*- FL
8	1		*ROCKER PANEL RH	Repair	1,799.60 FL	*- FL
9	1		*REAR DOOR RH	Dented	1,878.30 FL	*1,878.30 FL
10	2		*REAR DOOR BLACK STICKER RH	Necessary	90.00 FL	*50.00 FL
11	1		*REAR DOOR CHROME MOULDING RH	Not Necessary	180.80 FL	*- FL
12	1		*REAR DOOR OUTER HANDLE RH	Not Necessary	247.90 FL	*- FL
13	2		*REAR DOOR HINGE RH	Not Necessary	194.00 FL	*- FL
14	1		*REAR DOOR CHECKER RH	Not Necessary	119.70 FL	*- FL
15	1		*REAR DOOR INNER LOCK RH	Damaged	394.70 FL	*394.70 FL
16	1		*REAR DOOR LOCK CATCH RH	Not Necessary	46.00 FL	*- FL
17	1		*REAR DOOR WEATHERSTRIP RH	Cut	189.00 FL	*189.00 FL
18	1		*REAR DOOR INNER TRIM RH	Cracked	1,210.00 FL	*572.00 FL
19	1		*REAR DOOR REGULATOR MOTOR RH	Not Necessary	466.10 FL	*- FL
20	1		*REAR DOOR REGULATOR GEAR RH	Not Necessary	312.00 FL	*- FL
21	1		*REAR DOOR CHANNEL RH	Not Necessary	98.00 FL	*- FL
22	1		*REAR DOOR CHANNEL SEAL RH	Not Necessary	155.00 FL	*- FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	124.20 FL	*- FL
24	1		*REAR FENDER RH	Repair	1,892.00 FL	*- FL
25	1		*REAR ABSORBER RH	Not Necessary	339.50 FL	*- FL
26	1		*REAR WHEEL BEARING RH	Not Necessary	554.30 FL	*- FL
27	1		*REAR AXLE BEAM	Not Necessary	1,188.70 FL	*- FL
28	1		*WHEEL RIM RH	Cut	1,458.00 FL	*450.00 FL
29	1		*TAILLAMP RH	Not Necessary	778.00 FL	*- FL
30	1		*REAR BUMPER	Repair	654.00 FL	*- FL
31	2		*REAR BUMPER SIDE RETAINER	Not Necessary	195.40 FL	*- FL
32	1		*REAR BUMPER REFLECTOR RH	Not Necessary	110.00 FL	*- FL
33	1		*FRONT DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
34	1		*SET FRONT DOOR OUTER HANDLE CARBON	Not Necessary	450.00 FS	*- FS
35	1		*ROCKER PANEL SEALANT	Not Necessary	150.00 FS	*- FS
36	1		*REAR DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
37	1		*DOOR SUNVISOR	Necessary	400.00 FS	*120.00 FS
38	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER SEALANT	Not Necessary	120.00 FS	*- FS
41	1		*REAR FENDER INNER COWLING CLIP	Not Necessary	100.00 FS	*- FS
42	1		*REAR BUMPER CLIP	Not Necessary	50.00 FS	*- FS
43	1		*REAR BUMPER LOWER LIP CLIP	Not Necessary	20.00 FS	*- FS
44	1		*TAILLAMP CLIP	Not Necessary	30.00 FS	*- FS
45	1		*TYRE	Not Necessary	300.00 FS	*- FS
46	1		*REAR FENDER COWLING RH	Not Necessary	177.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$)	20,929.20	5,516.00
					- List Item Discount on L Items 20.00/20.00% (\$)	3,813.84	1,073.20
					Total Parts (\$)	17,115.36	4,442.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,REMOVAL AND REPLACING PARTS	New	1,500.00	900.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	1,000.00
3	TO APPLY TUFF COAT	New	180.00	80.00
4	PERFORM REAR WIRING CHECK	New	100.00	30.00
5	REMOVE & REFIX FRONT DOOR PART	New	200.00	80.00
6	REMOVE & REFIX REAR WINDSCREEN	New	250.00	0.00
7	REMOVE & REFIX REAR DOOR PART	New	200.00	0.00
8	REMOVE & REFIX REAR UNDER CARRIAGE	New	600.00	80.00
9	REMOVE AND REFIX UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	New	400.00	0.00
10	TO CHECK FOUR WHEEL ALIGHMENT	New	150.00	80.00
11	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
			Gross Labour Cost (\$\$)	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >