

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI21013066/KQY3E2

**Date:** 22/03/2022

### REFERENCE

Insured/Claimant: AUTOBAHN RENT A CAR PTE LTD Policy No: DMHCSNA00004192100  
Date of Loss: 18/12/2021 Nature of Claim: OD Claim No: SNM21D207427/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE7786B**  
Make & Model: TOYOTA SIENNA, 1.5 X CVT (A) Engine No: 2NR8569850  
Reg. Date: 01/08/2016 (Man. Year: 2015) Chassis No: NSP1707017485  
Colour: Metallic Black Odometer: 129144 km  
Engine Capacity: 1496 cc  
Market Value/New Car Price: S\$50,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15  
Front Left Side: Yokohama 2 mm Rear Left Side: Fireza 2 mm  
Front Right Side: Yokohama 3 mm Rear Right Side: Fireza 2 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--|-------------------|-------------------|-------------------|---------------|
| Parts                                    | 13,614.00         | 8,034.00          | 5,580.00          | 40.99         |
| Miscellaneous Items                      | 0.00              | 0.00              | 0.00              |               |
| Labour                                   | 806.40            | 315.00            | 491.40            | 60.94         |
| Paintwork Labour                         | 364.94            | 364.94            | 0.00              | 0.00          |
| Towing                                   | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>      | <b>14,785.34</b>  | <b>8,713.94</b>   | <b>6,071.40</b>   | <b>41.06</b>  |
| <b>Approved Total (Overridden) (S\$)</b> |                   | <b>6,950.00</b>   |                   |               |
| <b>- Excess (S\$)</b>                    | 0.00              | 2,000.00          | -2,000.00         |               |
| <b>(S\$)</b>                             | 14,785.34         | 4,950.00          | 9,835.34          | 66.52         |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,034.97          | 346.50            | 688.47            | 66.52         |
| <b>Nett Amount (S\$)</b>                 | <b>15,820.31</b>  | <b>5,296.50</b>   | <b>10,523.81</b>  | <b>66.52</b>  |

### INSPECTION

Date of Assignment: 22/12/2021 Present Location: Ding Auto Pte Ltd (HQ)  
Date Inspected: 24/12/2021 Inspected At: Ding Auto Pte Ltd (HQ)  
176 Sin Ming Drive #04-06, Sin Ming Autocare  
Singapore 575721  
Estimated Period of Repair: 10.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 22 Mar 2022)

**Parts:**      M1-MPV      TOYOTA SIENTA 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**      Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLE7786B)

**Validity:**      These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

| No. | Qty | Part No. | Particulars         | Condition | Repairer's               | Amount           |
|-----|-----|----------|---------------------|-----------|--------------------------|------------------|
| 1   | 1   |          | <b>*TOTAL PARTS</b> |           | 13,614.00 F              | *8,034.00 F      |
|     |     |          |                     |           | <b>Total Parts (S\$)</b> | <b>13,614.00</b> |
|     |     |          |                     |           |                          | <b>8,034.00</b>  |

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                             | Particulars                   | Lab.Type | Repairer's                      | Amount          |
|--------------------------------|-------------------------------|----------|---------------------------------|-----------------|
| <b><u>Paintwork Labour</u></b> |                               |          |                                 |                 |
| 1                              | Total Paint Labour            | New      | 235.20                          | 235.20          |
| 2                              | Total Paint Materials         | New      | 129.74                          | 129.74          |
| <b><u>Labour Items</u></b>     |                               |          |                                 |                 |
| 3                              | Total Panel/Mechanical Labour | New      | 806.40                          | 315.00          |
|                                |                               |          | <b>Gross Labour Cost (\$\$)</b> | <b>1,171.34</b> |
|                                |                               |          |                                 | <b>679.94</b>   |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >