

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013071/ATY3N2**Date:** 05/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00083022100

Claimant Vehicle No : FBR1712D **Insured Vehicle No :** SNA2992C

Date of Loss: 21/12/2021 Nature of Claim: TP Claim No: SNM21D207507/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR1712D**

Make & Model: YAMAHA NMAX155, 155cc Engine No: G3H6E0016986

Reg. Date: 09/03/2020 (Man. Year: 2019) Chassis No: MH3SG431000013532

Colour: Grey Odometer: 25434 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 110/70R13 Rear Tyre Size: 130/70R13

Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,338.00	1,494.00	844.00	36.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	430.00	170.00	28.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,938.00	1,924.00	1,014.00	34.51
Approved Total (Overridden) (S\$)		1,500.00		
Nett Amount (S\$)	2,938.00	1,500.00	1,438.00	48.94

INSPECTION

Date of Assignment: 23/12/2021

Date Inspected: 10/01/2022 Inspected At: Jec Autoservice (HQ)
1 KAKI BUKIT AVE 6 #02-11 AUTOBAY
Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source:	(Last Synchronised: 05 Apr 2022)	
Parts:	N/A	YAMAHA NMAX155 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR1712D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSHIELD	Cut	58.00 F	*58.00 FL
2	1		*HEADLAMP	Cut	308.00 F	*308.00 FL
3	1		*HEADLAMP SIDE COWLING LH	Cut	210.00 F	*210.00 FL
4	1		*FRONT LH SIGNAL LAMP	Cut	58.00 F	*58.00 FL
5	1		*FRONT LH SIDE GARNISH (BLACK)	Cut	148.00 F	*148.00 FL
6	1		*FLOOR PANEL GARNISH LH (BLACK)	Cut	195.00 F	*195.00 FL
7	1		*FLOOR PANEL LOWER GARNISH LH (GOLD)	Not Necessary	98.00 F	*- FL
8	1		*FLOOR PANEL GARNISH TOP COVER LH	Not Necessary	67.00 F	*- FL
9	1		*BALANCER LH	Cut	20.00 F	*20.00 FL
10	1		*BRAKE LEVER LH	Cut	23.00 F	*23.00 FL
11	1		*WING MIRROR LH	Cut	37.00 F	*37.00 FL
12	1		*FRONT FENDER	Repair	80.00 F	*- FL
13	1		*SIDE STAND LH	Not Necessary	66.00 F	*- FL
14	1		*MAIN STAND	Cut	87.00 F	*87.00 FL
15	1		*TAIL BOARD SIDE COWLING (GOLD)	Repair	194.00 F	*- FL
16	1		*ENGINE COVER LH	Not Necessary	158.00 F	*- FL
17	1		*N MAX EMBLEM	Necessary	48.00 F	*48.00 FL
18	1		*YAMAHA LOGO	Necessary	18.00 F	*18.00 FL
19	1		*FRONT NUMBER PLATE STICKER	Necessary	20.00 FS	*20.00 FS
20	1		*REAR BOX	Cut	280.00 FS	*220.00 FS
21	1		*REAR BOX BRACKET	Cut	150.00 FS	*150.00 FS
22	1		*155 STICKER	Necessary	15.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,338.00	1,615.00
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	121.00
Total Parts (S\$)	2,338.00	1,494.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR	New	250.00	200.00
2	SPRAY PAINTING	New	300.00	200.00
3	WIRING	New	50.00	30.00
			Gross Labour Cost (S\$)	430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >