

**Note: This document has not been finalised.**

## **LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance  
(Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Jenny Lew

Date: 11 Mar 2022

### **Preliminary Advice**

Insured	: XD7622D		
Vehicle No			
TP Vehicle	: SJS1825L	Accident Date	: 16/12/2021
No			
Make	: HONDA CIVIC	Assignment Date	: 23/12/2021
Date of	: 12/01/2022	Est. Duration of	: 3
Inspection		Repair	
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD		
	(PIONEER)		
	BLK 3 PIONEER ROAD NORTH, #01-18		
	SINGAPORE 628457		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,685.76
Revised Amount	:S\$	1,422.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,422.16

Lump Sum Repair	:S\$
-----------------	------

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$

COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.