

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 60388**
Date Estimated : **23/12/2021**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -
Arijit Roy
790 MOUNTBATTEN ROAD

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 437788

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD4787Y	WBAFP32080C8647	11/03/2011	523iA	162734

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper, front bumper absorber, attachment item cause by accident & make make good front left side panel.	1,275.00	0.00	1,275.00
To spray paint front bumper, front left side panel.	1,827.00	0.00	1,827.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	504.00	0.00	504.00
To check electrical wiring system at the front section	168.00	0.00	168.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	168.00	0.00	168.00
To replace left headlight.	457.00	0.00	457.00
To carry out body cavity preservation. (Per panel).	112.00	0.00	112.00
Sundries.	150.00	0.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
SUPPORT	4.85	2.00	0.00	9.70
FRT BUMPER TRIM PRIMED (PDC)	1,378.60	1.00	0.00	1,378.60
# BMW EMBLEM	72.85	1.00	0.00	72.85
# FRT LH WHEEL ARCH COVER	129.45	1.00	0.00	129.45
# LH COVER BOTTOM	66.75	1.00	0.00	66.75
LH BI-XENON HEADLIGHT	2,662.90	1.00	0.00	2,662.90
# LH FOG LIGHT GLASS LENS	287.90	1.00	0.00	287.90

SUPPLEMENTARY ITEMS

Total Labour :	4,661.00
Total Parts :	4,608.15
Total Labour & Parts :	9,269.15
Deduction for Excess :	
Total Repair Costs less Excess:	9,269.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

GST @7%:	648.84
Grand Total :	9,917.99

LOSS OF USE=\$120X 5 DAYS
GIA SEARCH FEE=\$2.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



supplementary

Estimate No. : **b1 60388**
Date Estimated : **23/12/2021**
Prepared By : **Brandon Chan Eng Meng**

- ESTIMATE REPAIR FOR -
Arijit Roy
790 MOUNTBATTEN ROAD

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 437788

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJD4787Y	WBAFP32080C8647	11/03/2011	523iA	162734

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

# BMW EMBLEM	72.85	1.00	0.00	72.85	REC
# FRT LH WHEEL ARCH COVER	129.45	1.00	0.00	129.45	TN
# LH COVER BOTTOM	66.75	1.00	0.00	66.75	BR
# LH FOG LIGHT GLASS LENS	287.90	1.00	0.00	287.90	BR

SUPPLEMENTARY ITEMS

Total Labour :

Total Parts : 556.95