LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd. Our File No: CS/CTI21013088/GVY3E2 3 Anson Road, #16-00 Springleaf Tower

Date: 08/06/2022 Singapore 079909

REFERENCE

Insured/Claimant: ZULKIFLI BIN ZAINI Policy No: DMPCSNW00190682001

Date of Loss: Nature of Claim: 15/12/2021 OD Claim No: SNM21D207340/C01/TAYHP

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJM2728J

Make & Model: MITSUBISHI COLT, 1.5 Turbo Version R (A) Engine No: 4G15JR7969

Reg. Date: 26/12/2008 (Man. Year: 2008) Chassis No: JMYXTZ27A8Z000153

Colour: Black Odometer: 212074 km

1468 cc **Engine Capacity:** Market Value/New Car Price: S\$46.000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Footbrake (Serviceable): Yes Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Average

CONDITION OF TYRES

Front Tyre Size: 205/45R16 Rear Tyre Size: 205/45R16 Front Left Side: Achilles 7 mm Rear Left Side: Achilles 7 mm Front Right Side: Achilles 7 mm Rear Right Side: Achilles 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,963.00	1,363.00	1,600.00	54.00
Miscellaneous Items	280.00	211.00	69.00	24.64
Labour	295.20	151.20	144.00	48.78
Paintwork Labour	362.08	362.08	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,900.28	2,087.28	1,813.00	46.48
Approved Total (Overridden) (S\$)		1,700.00		
- Excess (S\$)	500.00	0.00	500.00	100.00
(S\$)	3,400.28	1,700.00	1,700.28	50.00
+ GST 7.00/7.00% (S\$)	238.02	119.00	119.02	50.00
Nett Amount (S\$)	3,638.30	1,819.00	1,819.30	50.00

INSPECTION

Date of Assignment: 23/12/2021 Present Location: Auto Insure Pte Ltd (HQ) (Woodlands)

> Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane

Date Inspected: 24/12/2021 Inspected At:

Singapore 739145

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG **VERON CHEN** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Jun 2022)

Parts: 144 MITSUBISHI COLT 1.5 Turbo Version R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJM2728J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PARTS		2,510.00 F	*1,000.00 F
<u>Sup</u>	<u>pleme</u>	entary #1				
2	1		*FRONT FDR WHEEL GARNISH LH	Repeated	90.00 F	*- F
<u>Sup</u>	<u>pleme</u>	entary #2				
3	1		*FOG LAMP LH	Cracked	275.00 F	*275.00 F
4	1		*L/LWR TRIM INSERT	Missing	44.00 F	*44.00 F
5	1		*R/LWR TRIM INSERT	Missing	44.00 F	*44.00 F
F=Fra	nchise	part.		_		
				Total Parts (S\$)	2,963.00	1,363.00
			Report was unsubmitted d	uring this print-out.		

Recommended Miscellaneous Items

No Qty Particulars		Repairer's	Amount
Miscellaneous Items			
1 1 EXTRAS	_	280.00	211.00
	Sub Total (S\$)	280.00	211.00
Recommended Labour			
No Particulars	Lab.Type	Repairer's	Amount

No Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour			
1 LABOUR FOR SPRAY PAINTING	New	362.08	362.08
<u>Labour Items</u>			
2 LABOUR FOR PANEL BEATING	New	295.20	151.20
	Gross Labour Cost (S\$)	657.28	513.28

Report was unsubmitted during this print-out.

< END OF ESTIMATES >