

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ OD / ☐ P / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s AUTO INSURE

of

Insured:

Policy No. DMPCSNW00190682001

Claims No. SNM21D207340/C01/TAYHP

Sum Insured: Excess: 0

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value: \$46k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJM2728J Yr Regn: 26 Dec 2008

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MITSUBISHI COLT c.c. 1468

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 212074 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JMYXTZ27A8Z000153 *

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim ☐ STD A/Rim or

Tyre Size: F: 205/45R16

R: 205/45R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or ACHILLES

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 15/12/2021 D.O.I. 24-12-2021

Survey held at W/S 11:30

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRONT

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

6/6/22 LS \$1700 confirmed by email (Red 2290.28, 57%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 6/6/22-typist

Report Filed: Merimen

Lump Sum / LPA: LS \$1700

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Insp (\$☐ : Travel/End (\$

Survey Fee:

Transportation:

S + RS. SI

Photos

Other:

TOTAL