

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21013089/VQF3N2**Date:** 11/02/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MH000167
Claimant Vehicle No :	SHC1775E	Insured Vehicle No :	GBD7642G
Date of Loss:	21/12/2021	Nature of Claim:	TP
		Claim No:	M2105958

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1775E	Engine No:	2ZRS063152
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU603563941
Reg. Date:	07/09/2017 (Man. Year: 2017)	Odometer:	501921 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	206/60 R16	Rear Tyre Size:	206/60 R16
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,701.64	3,286.22	415.42	11.22
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,450.00	1,240.00	210.00	14.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,162.64	4,537.22	625.42	12.11
Approved Total (Overridden) (S\$)		3,500.00		
(S\$)	5,162.64	3,500.00	1,662.64	32.21
+ GST 7.00/7.00% (S\$)	361.38	245.00	116.38	32.20
Nett Amount (S\$)	5,524.02	3,745.00	1,779.02	32.21

INSPECTION

Date of Assignment:	24/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	22/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	4.0 days		

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 11 Feb 2022)**Parts:** 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHC1775E)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRT BUMPER ASSY	Cut	499.90 FL	-	*499.90 FL
2	10		*FRT BUMPER ASSY CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*HEADLAMP ASSY RH	Scratched	2,637.60 FL	-	*2,637.60 FL
4	1		*FRT BUMPER SIDE BRACKET RH	Necessary	82.30 FL	-	*82.30 FL
5	1		*FRT BUMPER GRILLE	Serviceable	301.90 FL	-	*- FL
6	1		*FRT BUMPER LOWER GRILLE	Serviceable	166.90 FL	-	*- FL
7	1		*FRT BUMPER FOG LAMP RH	Distorted	920.00 FL	-	*920.00 FL
8	1		*FRTBUMPER FOG LAMP GRILLE RH	Not Necessary	85.10 FL	-	*- FL
Supplementary #1							
9	1		*FRT FENDER EMBLEM RH	Necessary	86.50 FL	-	*86.50 FL
10	1		*FRT FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 F	-	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,902.20	4,348.30
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,200.56	1,062.08
Total Parts (\$\$)	3,701.64	3,286.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAYPAINT	New	300.00	250.00
3	CHECK WIRING	New	50.00	20.00
4	TUFF KOTE	New	50.00	20.00
Supplementary #1				
Labour Items				
5	PANEL BEATING	New	350.00	350.00
6	SPRAYPAINT - FENDER	New	300.00	250.00
Gross Labour Cost (\$\$)			1,450.00	1,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >