



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
<b>FASTECH AUTO PTE LTD</b> 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 ON BEHALF OF SITI ZULAINA BTNTI ABD KADIR			Ref: CS/TP21013095/Uvf3e2 Date: 12/01/2022 Code: TP130	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>		<b>Veh. Inspected</b>		SJP 1548C
<b>Policy No.</b>		<b>Coverage (\$)</b>		0.00
<b>Claim No.</b>		<b>Excess (\$)</b>		0.00
<b>Assign From</b>		<b>Assign Date</b>		24/12/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	HONDA ODYSSEY (A)	<b>c.c</b>	2354	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009	
<b>Chassis No.</b>	JHMRB38509C200472	<b>Colour</b>	PEARL WHITE	
<b>Odometer</b>	159541 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	215/55Z R17	CST	6 mm	
<b>L/H Front Tyre</b>	215/55Z R17	CST	6 mm	
<b>R/H Rear Tyre</b>	215/55Z R17	CST	6 mm	
<b>L/H Rear Tyre</b>	215/55Z R17	CST	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP, N/S BODY AND DUE TO FALLEN OBJECT. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	23/12/2021	<b>Inspection Date</b>	24/12/2021	
<b>Survey held at</b>	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>			<b>8 Working Days</b>	