



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 ON BEHALF OF SITI ZULAINA BTNTI ABD KADIR		Ref: CS/TP21013095/Uvf3e2 Date: 12/01/2022 Code: TP130	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	Veh. Inspected		SJP 1548C
Policy No.	Coverage (\$)		0.00
Claim No.	Excess (\$)		0.00
Assign From	Assign Date		24/12/2021
2. Vehicle Particulars & Condition			
Make & Model	HONDA ODYSSEY (A)	c.c	2354
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMRB38509C200472	Colour	PEARL WHITE
Odometer	159541 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55Z R17	CST	6 mm
L/H Front Tyre	215/55Z R17	CST	6 mm
R/H Rear Tyre	215/55Z R17	CST	6 mm
L/H Rear Tyre	215/55Z R17	CST	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP PANEL AND N/S BODY. THE CAUSE OF DAMAGES WAS DUE TO FALLEN OBJECT. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	23/12/2021	Inspection Date	24/12/2021
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	