LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd. 3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Cecilia Lee Date: 27 Dec 2021

Preliminary Advice

Vehicle No : GBE1797C Accident Date : 20/12/2021

: NISSAN NV350 Policy No. Make

DMCVSNW00108762100

Assignment

Date

: 24/12/2021

Excess

: S\$500.00

: 0

Date of : 24/12/2021 Est. Duration of

Inspection Repair

Inspection At: JIN AUTO SERVICES PTE LTD (DEFU)

BLK 14 DEFU LANE 10, #01-410/412

SINGAPORE 539195

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

TOTAL Repairer's Estimate (Gross) :S\$ LOSS

TOTAL **Revised Amount** :S\$ LOSS

:S\$ 0.00 Check Items (Estimated)

:S\$ Total 0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 30,000.00 COE / PARF Rebate :S\$ 16,630.00

Salvage Value :S\$

Margin for Repair :S\$ 13,370.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X	()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
()	Other comments :