

LC AUTOMOTIVE

OH BOON HONG
25 KAKI BUKIT ROAD4
05-26 SYNERGY @KB
Singapore 417800

TPAXA
Ashes

24th DECEMBER 2021

W PD2050422 2068332

Accident date: 24th DECEMBER 2021

Estimated repair cost for vehicle no: SGC812A MERCEDES BENZ C180

S/n	Qty	Items/Nett	U/price	Amount
1	1	Rear boot lid number plate		\$50.00 X
2	2	Rear Boot lid number plate lamp } NE NEW	\$112.00	\$224.00 X
3	1	boot lid kompressor emblem		\$165.00 X
4	2	Rear tail lamp RH cracked. NEW	\$785.00	\$1,570.00 785.
5	2	tail lamp bracket	\$168.00	\$336.00 X
6	2	rear lamp side garnish } NEW	\$215.00	\$430.00 X
7	2	rear tail Lamp hinges } NEW	\$188.00	\$376.00 X
8	1	rear reverse camera		\$900.00 X
9	1	Rear bumper Distorted		\$2,155.00 1668.
10	1	rear bumper lower trim Deformed		\$548.00 458.
11	2	Rear bumper centre bracket NEW	\$175.00	\$350.00 X
12	2	rear bumper side retainer RH and	\$170.00	\$340.00 75
13	1	Rear bumper packtronic sensor set 3 pieces damaged		\$1,200.00 750.
14	1	Rear bumper clips set NEW		\$50.00
15	2	Rear bumper chrome moulding side RH cracked	\$258.00	\$516.00 105.
16	1	Rear bumper chrome moulding- centre Cracked		\$385.00
17	1	Rear bumper towing cover missing		\$98.00 38.
18	1	Rear Bumper reinforcement Bent		\$1,080.00 745.
19	1	rear bumper member NEW		\$988.00 X
20	2	rear side under cover RH torn	\$368.00	\$736.00 135.
21	1	end panel Deformed		\$1,685.00 1360.
22	1	end panel top garnish NEW		\$215.00 X
23	1	Rear fender -RH Rys		\$2,155.00 X

Subtotal :- \$16,552.00

Labour charges

To remove & re-fix cushion

\$150.00 60

To remove & re-fix reverse sensor

\$120.00 60

To Check Wiring System

\$100.00 30

Tuff kote

\$120.00 80

Panel beating

\$1,200.00 700

Spray painting

\$1,200.00 700.

Subtotal :- \$2,890.00

Total:- \$19,442.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

6354
5898.60

1630

Total 7528.60

H/S: 6 KK 05 Days.