



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-9500000-9  
17 UBI ROAD 4  
SINGAPORE 408611, Tel no.: 6631 1188



# TOYOTA

*Not added  
all  
27/12/21  
6 days.  
Telukharo repair party.*

## ESTIMATE

Account Details	Account No.	Customer Details
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLP11	Mr Goh Eng Sie 53 Paya Lebar Crescent Singapore 536126 Mobile: 96707129
	Document No. 0	
	Document Date 24/12/2021	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ANH20R	PFXQK F3	05/05/2014	SKN0355Y	0	21493	67/TP/SKN0355Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD21H208331789	2AZJ080581	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP CLAIM TP-YP4451A ACC DATE:23/12/2021 DRIVE IN:24/12/2021 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				30.00
2	B	BP-LAB2 DRILL HOLE & INSTALL REAR REVERSE SENSOR				180.00
3	B	BP-LAB2 CHECK LIGHTING & CONDUCT WATER LEAK TEST				180.00
4	B	BP-LAB2 REMOVE & INSTALL REAR COMPARTMENT CARPET ,GARNISH AND TRIMMING TO ASSIST REPAIR				360.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)-TAILGATE, REAR END PANEL				60 120.00
6	B	BP-LAB2 REPLACE & INSTALL REAR WINDSCREEN GLASS				462.00
7	S	BP-SUBLET INSTALL REAR WINDSCREEN GLASS 3M SOLAR F ILM				350.00
8	B	BP-LAB2 TRANSFER & INSTALL COMPONENTS TO NEW TAI LGATE				360.00
9	S	BP-SUBLET TO RESET ECU AND REPROGRAMME				180.00
10	B	BP-LAB2 REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				720 3600.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
17 UBI ROAD 4  
SINGAPORE 408611, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1	Mr Goh Eng Sie	
		Document No. 0	53 Paya Lebar Crescent	
		Document Date 24/12/2021	Singapore 536126 Mobile: 96707129	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ANH20R	PFXQK F3	05/05/2014	SKN0355Y	0	21493	67/TP/SKN0355Y

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTEGD21H208331789	2AZJ080581	60	Sam San Joi	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
11	B	BP-RES2 RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS <i>590</i>		<i>2360</i>		3540.00
12	1	T52159-58916 COVER,RR BUMPER <i>DD box</i>	1.00	- 637.30		637.30
13	2	T52152-58010 R/R BUMPER EXTENSION, <i>DDNT</i>	1.00	- 59.80		59.80
14	3	T52155-58030 R/R SIDE BPR SUPPORT, <i>sent</i>	1.00	- 80.70		80.70
15	4	T52165-58020 A0 COVER, RR BUMPER, <i>DD</i>	1.00	- 206.10		206.10
16	5	T52155-58020 R/RR BUMPER SUPPORT, <i>sent</i>	1.00	- 46.70		46.70
17	6	S52161-0K040 CLIPS <i>all</i>	10.00	- 4.10		41.00
18	7	T52162-58010 A0 L/R BPR HOLE COVER, <i>re</i>	1.00	- 15.90		15.90
19	8	T58307-58038 PANEL SUB-ASSY, BODY <i>re</i>	1.00	1070.70		1070.70
20	9	T57081-58020 R/REAR BUMPER BRACKET, <i>re</i>	1.00	111.10		111.10
21	0	T67935-58022 A0 PLATE,BACK DOOR <i>re</i>	1.00	183.40		183.40
22	1	T67005-58120 REAR BACK DOOR PANEL, <i>rodging</i>	1.00	- 2120.20		2120.20
23	2	T67881-58020 RR BACK DOOR W/STRIP, <i>re</i>	1.00	412.60		412.60
24	3	T68105-58091 REAR BACK DOOR GLASS, <i>slatted</i>	1.00	- 1242.60		1242.60
25	4	T67750-58061 A0 BOARD ASSY, BACK <i>re</i>	1.00	710.60		710.60
26	5	T69350-28161 REAR BACK DR LOCK ASSY(W/PWR D <i>re</i>	1.00	495.10		495.10
27	6	T90975-02066 TOYOTA SYMBOL EMBLEM, <i>re</i>	1.00	- 72.20		72.20
28	7	T75441-58030 " ALPHARD" EMBLEM, <i>re</i>	1.00	- 68.70		68.70
29	8	T81551-58061 R/R COMBINATION LENS, <i>cre</i>	1.00	- 492.50		492.50

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less <i>6882</i> Amount Due

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
17 UBI ROAD 4  
SINGAPORE 408611, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details		Account No.	Customer Details	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP11	Mr Goh Eng Sie	
		Document No. 0	53 Paya Lebar Crescent	
		Document Date 24/12/2021	Singapore 536126	
			Mobile: 96707129	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2014	ANH20R	PFXQK F3	05/05/2014	SKN0355Y	0	21493	67/TP/SKN0355Y
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTEGD21H208331789	2AZJ080581	60	Sam San Joi	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
30	9	T81581-58121 R/REAR BOOT LENS, <i>one</i>	1.00	- 284.70	✓	284.70
31	0	T89997-58030 ANTENNA, ELECTRICAL	1.00	192.20	✗	192.20
32	1	T89341-76010 A1 SENSOR, ULTRASONIC <i>17</i>	2.00	392.80	✗	785.60
33	2	T89348-64030 A0 RETAINER, ULTRASONIC <i>17</i>	1.00	- 20.60	✓	20.60
34	3	T89348-30030 A1 RETAINER, ULTRASONIC <i>17</i>	1.00	- 20.60	✓	20.60
35	4	T21000-20 SIKA 182010 SIKA TACK GO! (BLA <i>17</i>	2.00	- 108.00	✓	216.00
36	5	T21000-22 SIKA 207. G+P ADHESIVE PRIMER <i>17</i>	1.00	- 200.00	✓	200.00

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_

12283.7

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Date:	Customer's Signature	Charge Summary	Total	19,148.90
	Please acknowledge receipt of vehicle		Parts 9,786.90 Labour 8,832.00 Sublet 530.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	1,340.42
				Less	0.00
				Amount Due	20,489.32

Customer Copy



# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
17 UBI ROAD 4  
SINGAPORE 408611, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details		Account No.		Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1		Mr Goh Eng Sie				
		Document No. 0		53 Paya Lebar Crescent				
		Document Date 04/01/2022		Singapore 536126 Mobile: 96707129				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2014	ANH20R	PFXQK F3	05/05/2014	SKN0355Y	0	21493	67/TP/SKN0355Y	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTEGD21H208331789		2AZJ080581	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	T76801-58110 A0 GARNISH SUB-ASSY <i>one</i>			1.00	2072.10	<del>---</del>	2072.10
2	2	T85242-58030 BLADE, RR WIPER <i>M/S</i>			1.00	60.30	<del>---</del>	60.30
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 2,132.40		
		Please acknowledge receipt of vehicle		Parts	2,132.40	GST 7.00%	149.27	
				Labour	0.00	Less	0.00	
				Sublet	0.00			
				Lubrication/Fluid	0.00			
				Others	0.00	Amount Due	2,281.67	

Customer Copy