


SIN HOCK LEE MOTOR REPAIR

UEN NO. 24928500B GST NO. M90366191A

BLK 51 UBI AVENUE 1 #01-09

PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Tel No. : 6282 6184 Fax: 6287 5977



CHEN BAIQUN

BLK 509 HOUGANG AVENUE 10

#04-109

SINGAPORE 530509

Estimate : ES210625-4162

Date : 25/06/2021

Vehicle Num. : SJF4162P

Make/Model : NISSAN LATIO 1.5L A

Chassis No : JN1BAAC11Z0007479

Accident Date : 22/06/2021

S/N	Quantity	Particular	Unit Price	Amount S\$
1	1	FRONT BUMPER ✓ DE	434.80	434.80 ✓
2	1 2	FRONT BUMPER SIDE RETAINER ✓ BR	21.90	43.80 21.9
3	1	FRONT BUMPER SPONGE X NN	205.20	205.20
		Sub-Total List Parts S\$:		683.80 456.7
		Discount 30%		-205.14
		Total List Parts S\$:		478.66 319.69
		NETT ITEMS::		
1	1	FRONT BUMPER CLIP SET ✓ NEC		35.00 30
		Sub-Total Nett Parts S\$:		35.00
		Discount 0%		0.00
		Total Nett Parts S\$:		35.00
		Total Parts S\$:		513.66
1	1	TO CHECK & RECTIFY WIRING SYSTEM X NN		80.00
2	1	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS		250.00 200
3	1	TO RE-SPRAY PAINTING ON THE CHANGED BODYPARTS, REPAIRED PORTION, & WHERE CONSISTENT TO THE ACCIDENT		300.00 200
		Labour Total S\$:		630.00

E. & O.E.

Sub-Total S\$: 1,143.66

GST 7% 80.06

Total S\$: 1,223.72

Gilbert Leon



for SIN HOCK LEE MOTOR REPAIR

749.69

Note: This is only an estimate based on our preliminary inspection and does not cover additional labour time or which may be required after the work has begun.

-20%: 600

2 Days