



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9953A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	COVER,FRONT BUMPER	BUCKLED	521.00	521.00
1	BRACKET,FRONT BUMPER SIDE,LH	SERVICEABLE	59.30	-
1	LINER,FRONT FENDER,LH	SERVICEABLE	210.30	-
1	FENDER SUB-ASSY,FRONT LH	TO REPAIR SEE LABOUR	977.80	-
1	FRONT FENDER EMBLEM LH	NECESSARY	54.60	54.60
1	UNIT ASSY,HEADLAMP,LH	SERVICEABLE	2,637.60	-
1	MIRROR ASSY,OUTER REAR VIEW,LH	SERVICEABLE	1,339.30	-
1	RIM	SERVICEABLE	1,900.10	-
	LESS 25% DISCOUNT		-1,925.00	-143.90
			5,775.00	431.70
	<u>SPECIAL NETT ITEMS</u>			
1	FRT FENDER CLIP (SN)	NOT NECESSARY	65.00	-
1	TYRE (SN)	SERVICEABLE	350.00	-
1	SET FRONT FENDER LINER CLIP (SN)	NOT NECESSARY	75.00	-
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	90.00	50.00
			580.00	50.00
	<u>LABOUR</u>			
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY,FRONT LH.		1,600.00	200.00
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.	NOT NECESSARY	240.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,600.00	440.00
	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-

Report Ref No. CS/AGI21013117/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	10.00
			4,380.00	650.00
GRAND TOTAL			10,735.00	1,131.70
RECOMMENDED COST OF REPAIRS				1,131.70

Report Ref No. CS/AGI21013117/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.