

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐

Preli. Report

☐

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS + SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



After 30/11/21 have G.I.D
Tailgate apply 50% because house OLD Daye.
17/1/22 4/5 @ 4200 informed After

cecilie

CHOO MOTOR SPRAY PAINTER
1 KAKI BUKIT AVE 6 #01-39 AUTOBAY
SINGAPORE 417883

Not Authorized
date
24/11/21
2/5 @ 4200
5 days

VEHICLE No: SMX 5053J

1PC	REAR WINDSCREEN MOULDING	121.50	rec	\$166.20	
1PC	TAILGATE	1193.40 50% =	rec	\$1,455.20	50% s/n 596.70
1PC	TAILGATE REAR LOGO		rec	\$48.00	
2PCS	TAILGATE REFLECTORS @\$341.60		11	\$683.20	x
1PC	TAILGATE 'SHUTTLE' EMBLEM		11	\$75.00	x
1PC	TAILGATE OUTER GARNISH		11	\$495.00	x
1PC	TAILGATE INNER LOCK	265.20	Def/hold	\$288.20	
1PC	TAILGATE INNER TRIM BOARD	428.10	De/B, n	\$455.10	
1PC	TAILGATE WEATHERSTRIP	185.40	11	\$232.80	
2PCS	TAILLAMP @ \$650.00		11	\$1,300.00	x
1PC	REAR BUMPER	936.00	11	\$1,215.10	
2PCS	REAR BUMPER SIDE RETAINERS @\$45.00		rec	\$90.00	
2PCS	REAR BUMPER REFLECTORS @\$75.00		11	\$150.00	x
2PCS	REAR BUMPER SIDE COVERS @\$111.00		11	\$222.00	x
1PC	REAR BUMPER INNER SPONGE		11	\$183.00	x
1PC	REAR END PANEL	615.00	11	\$755.20	
1PC	REAR END PANEL TOP GARNISH		11	\$248.70	
1PC	REAR END PANEL ANTENNA SENSOR		11	\$108.90	x
2PCS	REAR END PANEL SIDE EXTENSION PANELS @\$285.00		11	\$570.00	x
1PC	REAR EXHAUST		11	\$688.20	x
1PC	REAR FLOOR PANEL TOP BOARD		11	\$544.10	x
1PC	REAR FLOOR PANEL		11	\$1,140.20	x
1PC	REAR FLOOR PANEL TOOLS TRAY		11	\$652.30	x
				\$11,083.20	

S.NETT

1PC	REAR WINDSCREEN SEALANT	rec	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	rec	\$50.00	40
1SET	REAR BUMPER REVERSE SENSOR	Shops	\$280.00	200
1SET	TAILGATE INNER TRIM BOARD CLIPS	rec	\$50.00	
1PC	TAILGATE INNER 'AUTO TAILGATE' STICKER	11	\$60.00	x
1PC	REAR END PANEL SEALANT	rec	\$50.00	
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00	x
1PC	REAR BUMPER TOP CHROME MOULDING	one	\$280.00	200

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO TRANSFER TAILGATE MECHANISM	\$100.00	50
TO SPRAY RUST PROOFING	\$100.00	60

TO RESET & REPROGRAMME SYSTEM
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

800

TOTAL

\$120.00 50
\$1,200.00 600
\$1,500.00 700
\$15,523.20

7-2937-9
202
P. 2350-32
S.N. 1176.7
L- 1730

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5287.07
202/0
4208