

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21013119/RQF3E2

Date: 23/03/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 1001743375
Claimant Vehicle No : SKC9176X Insured Vehicle No : GBB567Y
Date of Loss: 23/12/2021 Nature of Claim: TP Claim No: 267334

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKC9176X**
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGBU294968
Reg. Date: 14/10/2011 (Man. Year: 2011) Chassis No: KMHDH41CMCU235450
Colour: Grey Odometer: 155173 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-----------------|-----------------|-----------------|--------------|
| Parts | 1,284.80 | 914.40 | 370.40 | 28.83 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,360.00 | 460.00 | 900.00 | 66.18 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 2,644.80 | 1,374.40 | 1,270.40 | 48.03 |
| Approved Total (Overridden) (S\$) | | 1,100.00 | | |
| (S\$) | 2,644.80 | 1,100.00 | 1,544.80 | 58.41 |
| + GST 7.00/7.00% (S\$) | 185.14 | 77.00 | 108.14 | 58.41 |
| Nett Amount (S\$) | 2,829.94 | 1,177.00 | 1,652.94 | 58.41 |

INSPECTION

Date of Assignment: 27/12/2021
Date Inspected: 28/12/2021 Inspected At: 48 Toh guan road east #01-141
Estimated Period of Repair: 2.0 days Repairer: Mtm Performance Auto Pte Ltd

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Mar 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKC9176X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|---|-------------------------------|
| 1 | 1 | | *FRONT DOOR RH | Bent | 998.00 FL | *998.00 FL |
| 2 | 1 | | *FRONT DOOR RH WEATHER STRIP | Not Necessary | 95.00 FL | *- FL |
| 3 | 1 | | *FRONT DOOR RH HANDLE ASSEMBLY WITH KEYLESS | Cracked | 235.00 FL | *145.00 FL |
| 4 | 1 | | *FRONT DOOR RH HINGE | Not Necessary | 58.00 FL | *- FL |
| 5 | 1 | | *FRONT DOOR RH LOCK | Not Necessary | 220.00 FL | *- FL |
| | | | | | Sub Total (S\$) | 1,606.00 1,143.00 |
| | | | | | - List Item Discount on L Items 20.00/20.00% (S\$) | 321.20 228.60 |
| | | | | | Total Parts (S\$) | 1,284.80 914.40 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|-------------------------------|---------------|
| Labour Items | | | | |
| 1 | PANEL BEATING FOR REPAIR | New | 600.00 | 200.00 |
| 2 | SPRAY PAINTING FOR REPAIR | New | 600.00 | 200.00 |
| 3 | REM-REFIT OF FRONT DOOR RH ITEMS TO FACILATE OF REPAIR | New | 160.00 | 60.00 |
| | | | Gross Labour Cost (\$) | 460.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >