

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 01 Mar 2022

Preliminary Advice

Insured : GBB567Y
Vehicle No
TP Vehicle No : SKC9176X
Make : HYUNDAI ELANTRA
Date of Inspection : 28/12/2021
Inspection At : MTM PERFORMANCE AUTO PTE LTD
48 TOH GUAN ROAD EAST #01-115 ENTERPRISE HUB
SINGAPORE 608586

Accident Date : 23/12/2021
Assignment Date : 27/12/2021
Est. Duration of Repair : 2

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,644.80
Revised Amount	:S\$	1,374.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,374.40
Lump Sum Repair	:S\$	1,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$

Margin for Repair :S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.