



# ALFRED AUTO

## Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00 E  
 Email: alfredauto@hotmail.com

Tyre & Sports Rim



Reference No.: 251221

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 25.12.2021

Aik Chin Hin Trading Hardware Pte Ltd  
 Blk 5022 #01-31 Ang Mo Kio Industrial Park 2  
 Singapore 569525.

Toyota Dyna

Estimate Repair Cost for Vehicle Reg. No: GBK 2047 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 Pc. Rear Carriage Floor Panel	HN		2,850.00 (S. Nett)	X
1 Pc. Rear Carriage Aluminum Floor Panel	SN		1,400.00 (S. Nett)	X
1 Pc. Rear Tail Gate	Dent		1,280.00	✓
4 Pcs. Rear Tail Gate Hinger	BT	@ 98.00	392.00	✓
2 Pcs. Rear Tail Gate Upper Lock	HN	@ 69.00	138.00	X
2 Pcs. Rear Tail Gate Side Hinger	HN	@ 125.00	250.00	X
2 Pcs. Rear Tail Gate Lower Stopper	SN	@ 48.00	96.00	X
1 Pc. Rear Tail Gate Aluminum Panel	HC		480.00	✓ SH 350.00
1 Pc. Toyota Sticker	HC		155.00 (Nett)	✓
1 Pc. Dyna Sticker	HC		68.00 (Nett)	✓ 12.00 SH
1 Pc. 70 KM/H Sticker	SH HC		12.00 (S. Nett)	✓
1 Pc. Step Holder Bracket	BT		180.00 (Nett)	✓ 50/- SH
2 Pcs. Rear Lamp	CT	251.10 @ 290.00	580.00	✓ 502.20
2 Pcs. Rear Lamp Panel	BT	@ 110.00	220.00	✓
1 Pc. No. Plate Holder Panel	BT		195.00	✓ 127.30
2 Pcs. No. Plate Lamp	HN	@ 58.00	116.00	X
1 Pc. No. Plate	BT		50.00	✓ 20/- SH
1 Set Reverse sensor	Dent		285.00	✓ 150/- SH
1 Pc. Reverse Camera	Dent		388.00	✓ 150/- SH
1 Pc. Spore Tyre Puller	BT / Dental		689.00	✓ 283.00
1 Pc. Rear Exhaust	BT		1,390.00	✓ 529.80
2 Pcs. Rear Exhaust Mounting	SN	@ 90.00	180.00	X
2 Pcs. Rear Exhaust Bracket	HN	@ 110.00	220.00	X
1 Pc. Front Panel	Dent		1,480.00	✓ 1194.30
1 Pc. Front Top Panel	HTA dent		510.00	X
1 Pc. Front Grille	CT		330.00	✓
1 Pc. Front Grille Logo	HC		118.50	✓ 68.00
1 Pc. Front Dyna Emblem	HC		169.80	✓ 69.30
10 Pcs. Front Grille clips	HC	@ 5.50	55.00	✓ 15/- SH
2 Pcs. Front Head Lamp	minuty crack	785.40 @ 699.10	1,398.20	✓
			1570.80	



# ALFRED AUTO

## Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00 E  
 Email: alfredauto@hotmail.com



1 Pc. Front Bumper <i>distress / many crack</i>	698.80 ✓	521.60
2 Pcs. Front Bumper Bracket <i>st</i>	@ 138.00	276.00 ✓
1 Pc. Front No. Plate <i>st</i>	50.00 ✓	20/- SW
1 Pc. Windscreen Rubber <i>st Hic</i>	499.80 ✗	228.90

List	Total (Panels / Parts):	<u>17,200.10 (SGD)</u>
<del>7593.20</del>	SH 809.00	=
25% 5694.90	=	

### LABOR CHARGES

To check wiring, remove & refit carriage wiring, Dashboard wiring & all affected area.	400.00	40/-
To remove & refit renew aluminum plate.	850.00	150/-
To remove & refit renew rear exhaust.	300.00	60/-
To remove & refit windscreen.	150.00	120/-
To remove & refit dashboard, panel brake & Clutch bracket & all affected area.	800.00	44
To remove & refit air-con cooling coil, bowler motor Set & top-up oil & gas.	580.00	44
To welding, knocking, straightening, repair & renew Front & rear accident damage affected area.	2,000.00	800/-
To respray painting on all accident affected area.	2,000.00	800/-
To rust proof all accident affected area.	250.00	40/-

Total (Labor Charges): 7,330.00 (SGD)

27/12/2021 @ 1500hrs

Not Andrew

4/5 hrs 7 days. Check part prices.

*(Signature)*  
myan

LKK And Page 2 of 3

8513.90  
4/5 6,800/-



# ALFRED AUTO

## Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538  
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E  
Email: alfredauto@hotmail.com

Tyre &  
Sports Rim



### TOTAL COST SUMMARY

PANELS / PARTS	17,200.10
LABOR CHARGES	7,330.00

---

**Grand Total: 24,530.10 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

For internet banking transfer – OCBC Current Account No. 620-453233-001 or  
PAYNOW UEN 39108900E

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.