



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI21013128/Atf3e2	
			Date: 22/02/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBS 4281E	Veh. Inspected	SKU 6963R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003497MFCE	Excess (\$)	0.00	
Assign From	JOANNE TAN JO ANN	Assign Date	27/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	AUDI A1	c.c	999	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WAUZZZ8X3FB024998	Colour	SILVER	
Odometer	80992 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/50 R16	MICHELIN	6 mm	
L/H Front Tyre	195/50 R16	MICHELIN	6 mm	
R/H Rear Tyre	195/50 R16	MICHELIN	6 mm	
L/H Rear Tyre	195/50 R16	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2021	Inspection Date	23/12/2021	
Survey held at	TICK HAI MOTOR & WELDING SERVICES BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	