

TICK HAI MOTOR & WELDING SERVICES
1 KAKI BUKIT AVE 6 #01-54 SINGAPORE 417883

TEL: 6842 9089 FAX: 6841 2869

REG NO : 48992400W

TP 1st Cap.
Denise.

Vehicle Number: SKU6963R
 Vehicle Model : Audi A1 SB 1.0 TFSI (PI)
 Manufacture Year : 2015
 Chassis : WAUZZZ8X3FB024998

S/N.	Item Description	Amount (\$)
1	Rear Bumper <i>Distorted</i>	\$ 1,395.90 ✓
2	Rear Bumper Diffuser <i>deformed</i>	\$ 407.13 ✓
3	Rear Bumper Reinforcement <i>Dented</i>	\$ 488.57 ✓
4	Rear Bumper Side Retainer (RH); <i>new</i>	\$ 56.02 X
5	Rear Bumper Clip x 1 set <i>new</i>	\$ 50.00 ✓
6	Rear Bumper Reflector (LH) (RH) <i>cracked</i>	\$ 53.50 ✓
		<i>2395.10</i>
		Total : \$ 2,451.12
		<i>2155.59</i>
		Less 10% : \$ 245.11
		Amount : \$ 2,206.01

S/N	Special Nett Item	Amount (\$)
1	Reverse Sensor x 2 pcs <i>1 piece dont</i>	\$ 359.55 ✓
		<i>179.77</i>
		Amount : \$ 359.55

Labour	Amount (\$)
To remove & reinstall reverse sensors	\$ 120.00 ✓ <i>50</i>
To check rear electrical wiring system	\$ 120.00 ✓ <i>30</i>
Labour to remove, cut, change & panel beating <i>480</i>	\$ 750.00 ✓ <i>200</i>
To putty and respray affected areas	\$ 650.00 ✓ <i>200</i>
Labour Total :	\$ 1,640.00
Total (Parts & Labour) :	\$ 4,205.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

total 2815.36
L/S: 2.2k.
02 Days