



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3235D

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | FRONT WING MIRROR ASSY RH | CRACKED | 670.00 | 670.00 |
| 1 | FRONT DOOR OUTER MOULDING | DENTED | 153.10 | 153.10 |
| 1 | FRONT DOOR | TO REPAIR SEE LABOUR | 2,256.40 | - |
| | LESS 20% DISCOUNT | | -615.90 | -164.62 |
| | | | 2,463.60 | 658.48 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | FRONT DOOR COMFORT STICKER (SN) | NECESSARY | 75.00 | 75.00 |
| | | | 75.00 | 75.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT DOOR . | | 280.00 | 280.00 |
| | SPRAY PAINTING (FRT PILLAR & FRT DOOR). | | 500.00 | 500.00 |
| | REMOVE/REFIX DOOR PARTS. | | 60.00 | 60.00 |
| | | | 840.00 | 840.00 |
| | GRAND TOTAL | | 3,378.60 | 1,573.48 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) | | | 1,200.00 |

Report Ref No. NS/INC21013130/Vqcn2

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.