

REG BY: Thevan

ntac

NS/INC21013130/Vqc

ASSIGNMENT

SHD.32350

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. MT/1155191-002

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs.

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD.32350

Yr Rogn:

7/7 1/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai 140

c.c 1685

Colour

blue

A/C: Insured / Std / NI / NA

Sp. Reading

883/99

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH1341UM64091862

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

206/60R16

R:

206/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

17/12/21

D.O.I.

17/12/21/1649

Survey held at

LDG

Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or

middle

o/s body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

no GIA provided

31/12/21 Thevan finalised with Mr Chiang LS \$1200. 2 days. (Red \$2178.60, 64%)

Date/Time File Pass to?

☐

: Prelim. Report

10/01 Typist

☐

: Final Report

Date/Time File Return to?

7

Days Of Repair:

2

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Visual and

Survey Fee:

Transportation:

___ S + RS ___ \$

Flims

Others

Total

Report Fee:

TP

1200

Date/Time: 17.12.2021 11:26

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4152858

JC NO305498225

CUSTOMER

MR/MS COMFORT TRANSPORTATION PTE LTD
CUSTOMER NO. 7010045
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL. (R) 65508755 (O)
(P)

DISCOUNT CARD NO.

REGN NO.

SHD3235D

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....

MODEL

I-40

DATE/TIME IN

17.12.2021 09:30

YR OF MANU.

07.07.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU091862

COMPLETION DATE/TIM


JOB DESCRIPTION

Accident Date: 17.12.2021
N. URE: 3P 17.12.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Name:

/C No.:

Vehicle No.:

SHD3235D

CHIANG

Vehicle No.:

SHD3235D

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

To be returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD3235D ✓

MAKE HYUNDAI

MODEL I-40

DATE 17/12/2021 06:40

MVA CHIANG/ NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	FRONT WING MIRROR ASSY RH			\$670.00
1	FRONT DOOR OUTER MOULDING			\$153.10
1	FRONT DOOR			\$2,256.40
	SUB TOTAL			\$3,079.50
	20.00%			\$615.90
	DISCOUNTED TOTAL			\$2,463.60
1	FRONT DOOR COMFORT STICKER			\$75.00
	Labour Charge			
	Panel Beating			\$280.00
	Spray Painting (Frt pillar & frt door)			\$500.00
	Remove/Refix door parts			\$60.00
	TOTAL LABOUR			\$840.00
	ESTIMATE TOTAL			\$3,378.60
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Thevan@LKKauto.com

8223 5769

17/12/21 1645

C/S after repair photo

2 days up ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: