

Our Job Ref No 305498229  
Date : 21/12/2021

## ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK  
Attn : THEVAN  
: SH 8122L

Fax :

DOA 16/12/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- FY 1767L
- The finalized amount shall be:
  - Spare Parts after List discount
  - Labour Charges

**Total for Part-By-Part Repair Cost**

  - Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20% **\$2,150.00**  
**Final Lumpsum Repair cost**
- Estimated normal period for repairs: 3 working days
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :  
Name : JUMANI  
Tel : 6214 8315  
Fax : 65468156

Signature :  
Name : THEVAN  
Date : 27/12/21

#### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	7.49 / 2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO SH 8122L ✓  
 MAKE HYUNDAI  
 MODEL IONIQ

DATE: 17.12.21

MVA JUMANI

DOA: 17. Dec. 2021

NTUC (48)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	BOOTLID COVER			\$2,480.40
1	REAR BUMPER ASSY			\$459.40
1	REAR BUMPER CENTRE MOULDING			\$451.25
1	REAR BUMPER BEAM			\$394.80
1	REAR BUMPER CLIPS			\$22.00
1	FOG LAMP			\$201.50
1	ANTENNA ASSY - SMARTKEY			\$40.50
	BOOTLID EMBLEM - IONIQ			\$31.30
	BOOTLID EMBLEM - HYBRID			\$24.30
	BOOTLID EMBLEM - H			\$28.00
	<b>SUB TOTAL</b>			<b>\$4,133.45</b>
	<b>LESS 20%</b>			<b>\$826.69</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$3,306.76</b>
	REAR NUMBER PLATE			\$50.00
	ADVERTISEMENT LOGO - FENDER			\$200.00
	ADVERTISEMENT LOGO - BOOTLID			\$100.00
	REVERSE SENSOR			\$180.00
	REAR BOOTLID COMFORT LOGO			\$30.00
	REAR BOOTLID TEL.NOS LOGO			\$30.00
	REAR BOOTLID APPS LOGO			\$40.00
	WINDSCREEN SEALANT			\$46.00
				<b>\$676.00</b>
	<b>Labour Charge</b>			
	PANEL BEATING			\$800.00
	SPRAY PAINT			\$600.00
	REMOVE / REFIX REVERSE SENSOR			\$50.00
	CHECK WIRING			\$50.00
	REMOVE / REFIX REAR WINDSCREEN GLASS			\$120.00
	<b>TOTAL LABOUR</b>			<b>\$1,620.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$5,602.76</b>
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Thuan@Lkhauto.lou  
 8223 5769

17/12/21 1615

LIS after repair photo  
 3 days swp ✓